

Status of HVFT


Adamo G., Franco S., Laura M.B.

02.06.2016

- 2.4m PE1000 rod broke during the cool down before insertion
- 2 Possible reasons:
 - PE1000 ordered from US
 - Mechanical Design
- Solution:
 - ➔ Design of the FT reduced in order to have 2000mm PE1000 insert (delivery is fast)
 - Cinel already got the HDPE
 - ➔ Preliminary Test with the NEW PE1000 in order to verify that the problem was in the material
 - Material already there and test will be done beginning of next week
- New Design of the HVFT already integrated in the 3D in order to verify additional Problems
- Insulated part is now 400mm shorter → Laura M.B did COMSOL simulation

Next Steps:

- If the problem was due to the PE1000 from US:
 - New 2m Long PE1000 will be manufactured
 - HVFT Stainless steel Pipe shortened
 - New longer stainless steel connection to the cathode
 - **We will get a new delivery date according to the modification (ASAP according to the test results)**
- In the meantime considering a possible delay (unknown now):
 - check the Cryogenic to verify a possible Late insertion of the HVFT (already discussed with A. Diaz)
 - get the detailed step by step installation schedule of the cryogenic



- Cryogenic pipe passing over the HVFT to the Cryopump is movable
 - Cryopump can be removed
 - Final design from DEMACO to verify (we assume that should be ok)

