

Production of the CADS spoke cavities and ancillaries, and lessons learned

Feisi He

On behalf of colleagues in IHEP SRF group
Institute of High Energy Physics (IHEP)




Outline

- Background
- Fabrication and quality control
- Vertical test statistics
- He vessel issues and solutions
- Tuner issues




Spoke012 cavity

14 cavities in 2 CM. Beam commissioned with 2mA CW proton from 3.2MeV to 10MeV



Layout of ADS injector I


	Spoke 012
β_0	0.14
Aperture-mm	35
E_p/E_{acc}	5.0
B_p/E_{acc} - $mT/(MV/m)^2$	6.9
G- Ω	60
R/Q- Ω	150
df/dp [Hz/mbar]	-40
df/dp [Hz/mbar] (measured)	-130~-83
LFD [Hz/(MV/m) ²]	-13





Spoke021 cavity

- 6 cavities in one CM. developed in IHEP, Assembled in IMP. Waiting for tunnel commissioning



	Spoke 021
β_0	0.24
Aperture-mm	40
E_p/E_{acc}	4.4
B_p/E_{acc} $mT/(MV/m)^2$	9.4
G- Ω	71
R/Q- Ω	191
df/dp [Hz/mbar]	-6
df/dp [Hz/mbar] (measured)	<-10





Outline

- Background
- **Fabrication and quality control**
- Vertical test statistics
- He vessel issues and solutions
- Tuner issues



Spoke cavities fabrication

- Three qualified vendors provided 16 spoke012 cavities and 10 spoke021 cavities in the production phase. 19 prototype cavities of 6 types of cavities were from 6 vendors.
- 2012, 1st spoke cavity fabrication started
- 2012.12, 1st spoke012 cavity VT
- 2013.9, 1st spoke012 cavity HT with all ancillaries
- 2013.10, 1st spoke021 cavity VT
- 2014.3-9, 4 prototype spoke012 cavities VT, first vendor verified
- 2014.9-2015.3, 4 prototype spoke021 VT, second vendor verified
- 2015.4-9, spoke021 He-vessel tested and modified
- 2014.9-2015.11, 3 batches of 16 production spoke012 cavities from 3 vendors VT
- 2014.12-2016.2, 2 batches of 8 production spoke021 from 2 vendors VT



哈爾濱工業大學
HARBIN INSTITUTE OF TECHNOLOGY





中國科學院高能物理研究所
Institute of High Energy Physics Chinese Academy of Sciences







Development of IHEP ADS SRF cavities



Certification from vendor
Eye inspection

Defect inspection and grinding before final EBW, size control, frequency control




Deep drawing, annealing, machining, frequency control, grinding, EBW





Quality control: frequency control





- Frequency sensitivity of trimming the central ring was calculated based on measured critical sizes.





Quality control: frequency control (2)

- F scattering induced by fabrication error is typically 2—4MHz(0.6-1.2%)
- Final EBW used to caused f scattering of 1.6MHz; it is 0.2MHz when stiffening ring were welded first.






Outline

- Background
- Fabrication and quality control
- **Vertical test statistics**
- He vessel issues and solutions
- Tuner issues



Post processing of Spoke cavities

- BCP in Ningxia OTIC; re-HPR and clean assembly in IHEP







VT results of the spoke012 cavities

- MP conditioned in 1 hour with variable coupler
- Eacc increased by 2 MV/m with better cooling
- 120C baking increases Q_0 by about 50-100%
- At 2K, Q_0 is 6 times higher, $B_p \sim 125$ mT achieved.




Spoke012 4.2K VT, Designed $Q_0 = 5 \times 10^8$ @ $E_{peak} = 31.5$ MV/m







Spoke021 testing results

- MP conditioned in 1 hour
- Design target consistently exceeded
- Bp of 120mT and Rres of 7nΩ achieved at 2K



Spoke021 4K VT, Designed $Q_0 = 5 \times 10^8$ @ $B_{peak} = 65$ mT







Outline

- Background
- Fabrication and quality control
- Vertical test statistics
- **He vessel issues and solutions**
- Tuner issues



Spoke012 He vessel

- Problem: way too huge df/dp (-130 than -40Hz/mbar)
- Mainly by deformation of beam pipe
- Solution: adding stiffeners to He vessel, and stronger TIG welding






Spoke021 He vessel

- Unexpected high df/dp
- df/dp is extremely sensitive to the depth of one weldment, which was switched from EBW to TIG
- Re-weld with EBW solved the problem

df/dp [Hz/mbar]	Before	After
021-5#	-60	0
021-6#	-40	-13
021-7#	-58	-12
021-8#	-82	-9
021-9#	-67	-15
021-10#	-65	-11

Weld depth[mm] (slide fit 0.2mm)	df/dp [Hz/mbar]
5	-1.0
4	-6.5
3	-16.2
2	-32.7
1	-64.4







Outline

- Background
- Fabrication and quality control
- Vertical test statistics
- He vessel issues and solutions
- **Tuner issues**



Tuner issue

- Switch from pushing to pulling help reduce df/dp
- Severe backlash and overshoot possibly caused by gears and joints
- They were replaced from service port, which helped more or less





Tuner issue (2)



	CM1-1	CM1-2	CM1-3	CM1-4	CM1-5	CM1-6	CM1-7	CM2-1	CM2-2	CM2-3	CM2-4	CM2-5	CM2-6	CM2-7
Overshoot [Hz]	55	105	5200/ 2995	1120/ 215	500	155	117.5	35	0	102	123	104.5	139	27.5



Thanks for your attention!