



# Cryomodule Lessons Learned

A. Klebaner, G. Wu

International Workshop on Cryomodule Design and Standardization

September 7, 2018



# Outline

---

- Introduction
- Lessons Learned during Cavity Production
- Lessons Learned during String Assembly
- Lessons Learned during Cryomodule Testing
- Lessons Learned from Cryomodule Transportation (skipped, see Peterson presentation)
- Summary

Major Lessons Only

# Outline


---

- Introduction
- Lessons Learned during Cavity Production
- Lessons Learned during String Assembly
- Lessons Learned during Cryomodule Testing
- Lessons Learned from Cryomodule Transportation (skipped, see Peterson presentation)
- Summary

# LCLS-II Cryogenic Systems overview:

35 Cryomodules  
(+2 3.9GHz CM)

Cryoplant:  
2 x 4 kW@2.0K  
3.7 kW nom. load



# Some Changes during the Production

---

- Added 5 additional 1.3 GHz CMs
  - 1 spare + 4 production extras
- Added 1 spare 3.9 GHz CM
  - Goal to select best 35 of 40 – 1.3 GHz and 2 of 3 3.9 GHz CMs for linac
  - Maintain extras for field replacement as necessary
- Ordered additional cavities to account for production yield
- Installation of fluxgate magnetometers in all CMs
- Optimized cavity processing recipes for cavity production
- Added cryomodule test cycles for cooldown optimization
- Increased vendor oversight for cavity production

# Cryomodule Progress

---

- 1.3 GHz CM Production
  - 29 of 35 1.3 GHz CMs are in production or complete
  - Six broken for various reasons
- 1.3 GHz CM Testing
  - 11+10 CM tests complete
  - Average  $Q_0 > 2.7e10$
  - Average Gradient  $> 16$  MV/m

# Cryomodule Production at Fermilab



Courtesy of Sam Posen

# Key Technical Challenges

---

- CM Assembly
  - Tight Schedule
  - Design changes
  - String leaks outside of the cleanroom
- CM Testing
  - Maintaining high  $Q_0$  in the CM
  - Field emission
  - Microphonics mitigation
  - HOM tuning / end group heating
  - Cooldown optimization
  - String leak after warm-up
  - Transportation



# Outline

---


- Introduction
- Lessons Learned during Cavity Production
- Lessons Learned during String Assembly
- Lessons Learned during Cryomodule Testing
- Lessons Learned from Cryomodule Transportation (skipped, see Peterson presentation)
- Summary

# Nitrogen Doped Cavity Challenges

---

- Cavity production issues:
  - Poor flux expulsion material resulted cavity performance below specification in cryomodule
- Lessons learned
  - Improved understanding of niobium flux expulsion
  - Improved material/cavity processing recipe to recover flux expulsion capability.


# RI: $Q_0$ Results



- RI has completed fabrication of original order of 133 cavities
- 121 cavities have been tested so far at JLab and Fermilab
- TD Cavities 900/200 preparation consistently exceed LCLS-II spec

Slide by Dan Gonnella of SLAC


# RI: $Q_0$ Results



- RI has completed fabrication of original order of 133 cavities
- 121 cavities have been tested so far at JLab and Fermilab
- TD Cavities 900/200 preparation consistently exceed LCLS-II spec
- NX Cavities at 900°C have middling results

Slide by Dan Gonnella of SLAC

# RI: $Q_0$ Results



- RI has completed fabrication of original order of 133 cavities
- 121 cavities have been tested so far at JLab and Fermilab
- TD Cavities 900/200 preparation consistently exceed LCLS-II spec
- NX Cavities at 900°C have middling results
- 950 and 975°C have further improved upon the NX cavities' performance

Slide by Dan Gonnella of SLAC

# Outline


---

- Introduction
- Lessons Learned during Cavity Production
- Lessons Learned during String Assembly
- Lessons Learned during Cryomodule Testing
- Lessons Learned from Cryomodule Transportation (skipped, see Peterson presentation)
- Summary


# J1.3-06 Status

## J1.3-6

- Accidentally vented during preparation for leak check of 2 phase circuit
  - GHRP cap slipped and impacted right angle valve
  - String fast bled up to just under 100 torr.
- Cavity and couplers will require reprocessing



9/7/17 12:31	7.05	8.91E-09
9/7/17 12:41	7.05	8.91E-09
9/7/17 12:51	7.05	8.91E-09
9/7/17 13:01	7.05	8.91E-09
9/7/17 13:11	7.05	8.91E-09
9/7/17 13:21	7.05	8.91E-09
9/7/17 13:31	7.05	8.91E-09
9/7/17 13:41	7.05	8.91E-09
9/7/17 13:51	7.05	8.91E-09
9/7/17 14:01	7.05	8.91E-09
9/7/17 14:11	0.05	8.91E-09
9/7/17 14:21	0.05	8.91E-09
9/7/17 14:31	0	1.00E-01
9/7/17 14:41	0	1.00E-01
9/7/17 14:51	0	1.00E-01
9/7/17 15:01	0	1.00E-01
9/7/17 15:11	0	1.00E-01



Courtesy of Bob Legg of JLAB


# J1.3-06 Lessons Learned

New assembly procedure and tooling for GHRP cap installation at WS3 and WS5.

- Portable lift used to both lift GHRP cap and protect the Right Angle Valve; Safer for both employees and equipment.
- Looking into a plug with o-ring to replace GHRP cap for vacuum leak checks. Lighter, safer.



Metal bellows covers put in place to prevent accidental venting during prep for testing.






# F1.3-03 Cold Leak Developed

## F1.3-03

- Cold Leak Discovered during Cryomodule Warm up
- BPM Feedthrough flanges leaked
  - Three out of four seals leaked
  - Leak rate was  $\sim 8.5e-5$  mbar.L/sec
    - Leak was considered too big for clean beam line.
    - Decision was made to disassemble
- Possible stress on magnet spool pieces
- Grade 2 Titanium bolts did not provide sufficient sealing force.



## F1.3-03 Lessons Learned

### F1.3-03


- Replaced Grade 2 titanium bolts with Gr5 titanium studs.
- Increase the torque strength from 12 to 16 N.m
- Measure seal crush to ensure sufficient sealing cross section
- Improved procedure to avoid any stress to the BPM/magnet spool beam pipe.



# F1.3-03 HOM Feedthrough Thermal Strap Loose

## F1.3-03

- CAV3 quenched prematurely at 11 MV/m.
  - HOM end group heating




Washer  
loose

Thermal braid  
head completely  
loose

## F1.3-03 Lessons Learned


### F1.3-03

- Improved procedure to double check the integrity of the HOM thermal Straps



# F1.3-06 BPM Bolts Loosened

Courtesy of A. Burrill of SLAC



## F.13-06 BPM Lessons Learned

---

In addition to lessons learned as in F1.3-03:

- Added QC step in traveler to inspect all fasteners and their torques both in component level, as well as completed string assembly.

# J1.3-09 and J1.3-11 Helium Vessel Bellows Damaged

- J1.3-09 Bellows was found damaged on 5 July,
  - Visual inspection of all bellows on in process cryomodules (J1.3-09-11-12-13) followed
  - We found one additional bellows damaged on J1.3-11
  - Completed cryomodules (J1.3-02 – J1.3-07) will be inspected during subsequent work
  - JL1.3-08 and JL1.3-10, were in the process of acceptance testing, no leaks found



J1.3-09

J1.3-09 damage was found after a failed leak check and disassembly of the cryomodule

J1.3-11 was in an earlier stage of assembly and the damage was found during a visual inspection

Courtesy of E. Daly of JLAB



J1.3-11

# J1.3-09 and J1.3-11 Lessons Learned

- The JLab team has extended the risk matrix to all bellows in the cryomodule
  - Continuous improvement extends this to the cryomodule as a whole
  - FNAL will be included
- Apply lessons learned to other cryomodule production activities
  - CEBAF cryomodule production and rework
  - Cryomodules for other projects (SNS PPU, LCLS-II HE)
- Training matrix developed as part of the improved work controls identifies individual's qualifications
- Matrix is now the basis for staff development plans and will be a continuing part of the cryomodule production at JLab
  - Every supervisor has the matrix and only assigns work to qualified technicians
  - Every technician and supervisor has their own qualification matrix
  - Each individual is expected to know their qualifications and work only those activities they are qualified for

Courtesy of E. Daly of JLAB



# Outline

---

- Introduction
- Lessons Learned during Cavity Production
- Lessons Learned during String Assembly
- Lessons Learned during Cryomodule Testing
- Lessons Learned from Cryomodule Transportation (skipped, see Peterson presentation)
- Summary

# Microphonics Sources and Mitigations

---

- Cryogenic Valve Plumbing
  - Thermal Acoustic Oscillations in the Valve Stems
  - Helium Leakage into Cooldown Circuit
- Cavity 1 Mechanical Support
  - Modification and Retrofit Options

# Cryogenic Valve Plumbing – Improved Valve Stems



- TAOs are a pressure/temperature oscillation in cryogenic lines (in this case, valve stems)
  - During testing, wipers were added to close space in valve stem, acting as a damping term for the TAOs
  - Significant improvement in heat load and microphonics levels and stability for *both* F1.3-01 and J1.3-01
  - Optimized valve stems with wipers were used during F1.3-02 testing, *and will be used going forward for both labs*
    - 4-5 wipers, positioned to keep temperature ratio  $<4$  as recommended by literature
    - Radiation hard material (PEEK)



Optimized wiper placement going forward



# Cryogenic Valve Plumbing – Reverse Flow Path

- Test results show valve reversal (lower press in stem) significantly reduces/eliminate TAOs there
  - F1.3-01 configuration has valve stem at supply pressure (~3 bar)
  - Reversing flow will lower this pressure to sub-atmospheric, requiring guard gas to prevent contamination
  - All cryomodules will have guard gas, reversed valves
- Additional effort to mitigate TAOs in cryogenic distribution system should improve inlet temperature at test stand



# Valve Modification Improvement

- Comparing performance of the standard cryogenics configuration, the microphonics environment in the F1.3-02/03/04 is a factor of  $\sim 10$  improved
- Significant improvements in stability of the system, leading to a far more predictable detuning environment





PCM As Cooled Down

After Improvements  
F1.3-03

# Cryogenic Valve Plumbing – Cooldown Valve Leakage

- F1.3-04 presented with higher than expected microphonics, worsening as the cryomodule thermalized
- Noise was narrowband and showed complex spatial and spectral distribution in cryomodule
- Testing showed strong correlation with cooldown circuit, eventually proven to be coherent bubbling due to cooldown valve leakage
- Swapping valve stem returned expected performance, although testing schedule prevented detailed studies
- Tails seen in 'post-swap' data are likely due to continued thermalization of cryomodule after cooldown
- Additional QA check step now included to prevent valve leakage in the future





Thermalized Detuning

Post CD Stem Swap

# Cavity 1 Mechanical Connections – Mitigation

## Beamline Gate Valve Bellows

- Replacing spool piece between cavity 1 and gate valve with a bellows is non-trivial
- Corrective fix includes extending t arms with fixture to connect to gate valve
  - When replacing spool piece with bellows, fixture fully supports gate valve
  - Current supports are long arms connected to the 300 mm pipe with needle bearing for the longitudinal motion
- With gate valve is supported by frame/helium vessel, the spool piece can be replaced with a bellows to separate mass from cavity/tuner system
- First cryomodule with bellows to be tested will be F1.3-06 (on deck at FNAL)



# Outline

---


- Introduction
- Lessons Learned during Cavity Production
- Lessons Learned during String Assembly
- Lessons Learned during Cryomodule Testing
- Lessons Learned from Cryomodule Transportation (skipped, see Peterson presentation)
- Summary



# F1.3-05 and F1.3-06 Coupler Bellows Cracked during Transportation



Cavity 4



Cavity 5




Photo 8: Three more independent fatigue cracks (circled in red) around the secondary fatigue crack.

- Failed bellows examined after sectioning them:
- SLAC (Chris Pearson) Report on Cavity 4 Bellows: “*This is an example of **high stress low cycle fatigue**. That is, the material at the fracture location experienced multiple bending stress cycles at or above the yield strength, work hardening locally and eventually failing in a brittle manner.*”
- SGS report on Cavity 5 Bellows: “*Fatigue fracture initiated on the outside surface at multiple locations at grain boundaries that were infiltrated with braze metal. Uni-directional bending stresses initiated and propagated the multiple fatigue cracks completely through the bellows.*”

Courtesy of C. Adolphsen of SLAC

## **F1.3-05 and F1.3-06 Lessons Learned**

---

See Tom Peterson's slides.

# Summary

---

- A few significant cryomodule incidents have occurred during LCLS-II Cryomodule production.
- Incidents have been addressed.
- Lessons learned greatly benefit future projects such as PIP-II.