

Updates on Noise Filtering

Carlos Sarasty (University of Cincinnati)

Wenqiang Gu (BNL)

Zeyuan Yu (BNL)



Outline

- ❖ “Bipolar” noise
- ❖ Noisy / Bad channels

protoDUNE geometry

APA5 US-DaS FEMBs 501-520 TPS1 TPC 2 (3) FEMB IDs 20-39 1st channel: 2560	APA6 MS-DaS FEMBs 601-620 TPS3 TPC 6 (7) FEMB IDs 60-79 1st channel: 7680	APA4 DS-DaS FEMBs 401-420 TPS5 TPC 10 (11) FEMB IDs 100-119 1st channel: 12800
APA3 US-RaS FEMBs 301-320 TPS0 TPC 1 (0) FEMB IDs 0-19 1st channel: 0	APA2 MS-RaS FEMBs 201-220 TPS2 TPC 5 (4) FEMB IDs 40-59 1st channel: 5120	APA1 DS-RaS FEMBs 101-120 TPS4 TPC 9 (8) FEMB IDs 80-99 1st channel: 10240

https://wiki.dunescience.org/wiki/ProtoDUNE_geometry

Top view  z



Noise history







run number	HV	SSP	config	date	comment
5414	180	on	np04_WibsReal_Ssps_BeamTrig1GeV_00012		
5298	140	on	np04_WibsReal_Ssps_BeamTrig1GeV_00008	Oct 15	good
HV supply replacement 2018-10-17 15:25 https://pdspelog.web.cern.ch/elisa/display/8127					
5376	180	off	np04_WibsReal_Ssps_BeamTrig1GeV_00010	Oct 17	good, Run taken with 2 APAs and new power supply
5386	180	on	np04_WibsReal_Ssps_BeamTrig1GeV_00011	Oct 17	nosi, SSP on but SSP503 off
5387	180	on	np04_WibsReal_Ssps_BeamTrig1GeV_00011	Oct 17	noisy, SSP on but SSP503 off
6129	180	on	np04_WibsReal_Ssps_CRT_prescale3_00003	12-11	
6141	180	on	np04_WibsReal_Ssps_CRT_prescale3_00003	12-11	noisy
6142- 6148			ToyComponent_EBwriting00026		
6149- 6154			np04_felix_hit_find_00002		
6154	180	off	np04_felix_hit_find_00002	12-12	
6155	130	off	np04_WibsReal_Ssps_CRT_prescale3_00003	12-12	good
High Voltage supply replacement: https://pdspelog.web.cern.ch/elisa/display/9786					
6156	180	off	np04_WibsReal_Ssps_CRT_prescale3_00003	12-12	good
6157	180	off	np04_WibsReal_Ssps_CRT_prescale3_00003	12-12	good
6158	180	on	np04_WibsReal_Ssps_CRT_prescale3_00003	12-12	good
6212	180	on	np04_WibsReal_Ssps_CRT_prescale3_00003	12-17	good
6303	180	on	np04_WibsReal_Ssps_CRT_prescale3_00003	Jan 12	many missing channels

Channels with high RMS (Run 5424)

- ❖ Run 5424 Event 40460
- ❖ Drift side wires (Collection plane only)








		BadCh
➤	APA 3 tpc 1	12
➤	APA 5 tpc 2	59
➤	APA 2 tpc 5	15
➤	APA 6 tpc 6	75
➤	APA 1 tpc 9	0
➤	APA 4 tpc 10	29

- ❖ 190 noisy channels




APA 5


- ❖ ~59(46) bad channels in tpc 2(3)
- ❖ ~105 channels display noise at ~ 0.0518, 0.1036, 0.1554, 0.2072 ... MHz (Harmonics of 0.0518 MHz)
- ❖ Abnormal waveform



Run 5424




APA5	APA6	APA4
US-DaS	MS-DaS	DS-DaS
FEMBs 501-520	FEMBs 601-620	FEMBs 401-420
TPS1	TPS3	TPS5
TPC 2 (3)	TPC 6 (7)	TPC 10 (11)
FEMB IDs 20-39	FEMB IDs 60-79	FEMB IDs 100-119
1st channel: 2560	1st channel: 7680	1st channel: 12800
APA3	APA2	APA1
US-RaS	MS-RaS	DS-RaS
FEMBs 301-320	FEMBs 201-220	FEMBs 101-120
TPS0	TPS2	TPS4
TPC 1 (0)	TPC 5 (4)	TPC 9 (8)
FEMB IDs 0-19	FEMB IDs 40-59	FEMB IDs 80-99
1st channel: 0	1st channel: 5120	1st channel: 10240




- ❖ The excess noise in adjacent wires from the same tpc is isochronous e.g (ch 9280, 9281, 9284)
- ❖ Distant wires from the same tpc display a phase offset, also the magnitude is decreasing as we move from left to right e.g (ch 9280 and ch 9727)

After HV replacement on 10/17/18

Run 5424 October




Run 6141 December




❖ This problem shows up after the HV replacement on 10/17

Before HV supply replacement on 12/12/18

Run 6141 SSP ON 12/11




Run 6155 SSP OFF 12/12



❖ The noise is reduced when SSP's voltage is OFF


Right before and right after HV replacement on 12/12

Before Run 6155 SSP OFF 12/12



Run 6156 SSP OFF 12/12


After




❖ After the HV supply was replaced we observed only some channels with the bipolar noise

After HV replacement

Run 6156 12/12 SSP OFF




Run 6158 12/12 SSP ON




- ❖ Both SSP on and off won't give such noise, although we still see a few channels with this noise e.g ch 14400

Another Example

Before (run 5424)





After (run 6212)



❖ In this example the noise is significantly reduced after the HV supply replacement


RMS distribution




- ❖ After HV replacement on 12/12 many channels show an ADC rms less than 4

Preliminary noise filtering

Before filtering




Frequency domain




The problem is significantly suppressed after zeroing-out spikes in frequency domain


After filtering



Before and after filtering











Before and after filtering





Other bad channels?

Run 6212







Summary

- ❖ The “bipolar” noise is significantly reduced after the HV module replacement (12/12/2018)
 - Although a few channels still have the problem (e.g. ch 14400)
- ❖ New bad/noisy channels were found in recent data
- ❖ Suggestions and comments are more than welcome

THANKS!