


Abstract

PAL-XFEL(Pohang Accelerator Laboratory X-ray Free Electron Laser) started RF conditioning in October 2015 and has been operating reliably for ~ 4 years. The machine's LLRF and SSA systems contributed to the stable operation of PAL-XFEL with over 99% availability. The LLRF and SSA systems showed some problems in rare cases. The delay caused by the problem is very small, but PAL-XFEL can stop working. Some issues have been identified and resolved. We want to share the experience.




PAL-XFEL Overview

1

Main parameters


Parameter	Unit	Design (Hard/Soft)	Hard/Soft
Charge/bunch	nC	0.2	0.18
Slice emittance	mm-mrad	0.5	0.55
e- energy	GeV	10/3.15	9.47/3.0
Pulse repetition	Hz	60	60
e- peak current	kA	3.0/2.5	2.5/2.2
FEL gain length	m	3.6/1.8	3.61/2.08
FEL λ	nm	0.1/1.0	0.104/1.52
Photons/pulse	1011	1.8	10.0



Linac parameters

Parameter	Value
Linac type	Normal-conducting
Frequency	S-band (2.856 GHz; Gun, ACC, Deflector), X-band (11.424 GHz, linearizer)
Gun	S-band 1.6 cell photo-gun
Accelerating cavity	S-band 2/3 π mode
Total RF stations	51 (50 : S-band, 1 : X-band)
Cavities per klystron	1 ~ 4
Form of RF station	1 klystron(25 ~ 80 MW, ≤ 4 us, ≤ 60 Hz), 1 High-Voltage(HV) modulator, 1 SSA(pre-amplifier), 1 LLRF & 1 temperature-controlled rack (TC Rack)

RF station



Definition of Availability

2

A "full system" is considered as single body consisted of 51 units corresponding to each RF station. So, A defect of a certain unit is counted as a defect of the full system

T_{tot_plan} ≡ the total time planned (Total period – Maintenance period)
T_{tot_def_st} ≡ the total delayed time due to defects of a specific unit.

(Station) Availability(%) ≡ $(1 - \frac{T_{tot_def_st}}{T_{tot_plan}}) * 100(\%)$

(System) Availability(%) ≡ $(1 - \frac{\sum_{st=1}^{51} (T_{tot_def_st})}{T_{tot_plan}}) * 100(\%)$


∴ (System) Availability ≤ (Station) Availability

System availability is not equal to beam availability because the PAL-XFEL beam can usually be supplied with normal stations when some stations are down(about 5~10 stations are spares).


LLRF... system availability

System	(System) Availability for 2019		
LLRF	99.6 %	99.4 %	97.2 %
SSA	99.8%		
TC Rack	97.8 %		


Station availability (LLRF)



Station availability (SSA)




Station availability (TC Rack)



Issue #1 (LLRF) : PPC Freezing

3



Symptom :


- 1) EPICS disconnection
- 2) PPC freezing
- 3) PPC shutdown
- 4) Occurred randomly and rarely
- 5) 1 occurrence/station for 9 LLRF units this year (most frequent problem of LLRF)

First aid :

- 1) Reboot of PPC
- 2) Irrecoverable cases by reboot → replacement of LLRF unit

* PPC : Panel PC or Industrial PC

- In non-recoverable cases, the cause was PS degradation
- From a simple current analysis, the cause was judged by the use of PS more than 70% of the indicated capacity.



Occurrence before/after PS replacement

RF st.	Before	After
L1-1	Irrecoverable	
XLIN	1	1
L2-1	1	
L2-3	Several times	
L2-5		1
L2-8		1
L2-10	1	
L4-1		1
L4-10		1
L4-15	1	
L4-20	Irrecoverable	
L4-23	Irrecoverable	

Issue #2 (LLRF) : Incomplete Connection

4



Symptom :

- 1) LLRF output failures(no output)
- 2) PSK switching failures
* PSK : Phase Shift Keying for SLED operation
- 3) Wrong temperature values
- 4) Common features :
* Normal operation until the moment of failure
* occurred randomly and suddenly
- 5) In total, less than 5 times for 4 years

First aid :

- 1) Replacement of the LLRF unit with a spare unit

Internal view of a LLRF



- Identified common cause : incomplete connection of connectors within LLRF case

- There are many RJ45 connectors and 2 HDMI connectors for compact cable connection and high-speed operation within PAL-XFEL LLRF box.

- The connectors prove very efficient and compact but not perfect.

- All problematic sets are recovered by reconnection of the connectors.

- We will search for better solution like better vendors or new kinds of connectors.

Issue #3 (SSA) : Abnormal interlock

There are many interlock items(10 items) in PAL-XFEL SSA.

Occasionally, some interlocks are occurred like "over repetition" or "over current"

Sometimes, RS-232 communications are lost between the LLRF and the SSA pairs

Occurrence frequency : once/6~12 months

First aid :

Operator manually unlocks interlock and resumes beam operation in control room

Reboot of the SSA

At last, important hints were found this year

Jan./2019

L3 – A2 SSA

Over Current interlock : several times
Replaced by a spare SSA

Normal operation without the interlock in test room
→ Interlock at the klystron gallery is a fake interlock due to noise

Mar./2019


L4 – 2 SSA

Over Repetition interlock : several times
It suddenly appeared after the February maintenance period.

Job in Feb. maintenance :
Reinstallation of LLRF and reconnection of cables


Solved by rearrangement of the RS-232 cable path between the LLRF and the SSA, and no problems until now

- It is inferred from these hints that the strong noise from HV modulator affected RS-232 communication.
- For the L4-2 case, the abnormal interlock was disappeared as shown figure below, but some other cases, the reverse showed positive effects.
- As long-lasting solutions, noise countermeasures will be in place or more noise-resistant communications will be applied in the next version.



Issue #4 (TC Rack) : Water leakage

6



The occurrence frequency of water leakage is increasing this year → a serious problem

Treatment :
Replacing the leak exchanger to a spare (takes 1~2 hours/replace & only 2 spare parts available)

Occurrence of leak

Year	2018	2019
Station	1~12	1~8
L0-02		1
L2-02	1	
L2-04	1	
L2-05		1
L2-08		1
L4-15		2
Sum	2	5

For more reliable operation, the following works proceed :

- 1) Preparing more spare exchangers
- 2) Redesigning heat exchangers
- 3) Developing a rack easier to replace heat exchanger