

Advanced Examination of Nb₃Sn Coils and Conductors for the LHC luminosity upgrade: Computed Tomography and Materialographic Analyses

S. Sgobba¹, G. Arnau Izquierdo¹, I. Aviles Santillana¹, B. Bulat², M. Celuch¹, M. Crouvizier¹, A. Devred¹, S. Izquierdo Bermudez¹, A. Milanese¹, A. Moros¹, F. Savary¹, E. Todesco¹

¹European Organization for Nuclear Research, Geneva, Switzerland

²FOSELEV Suisse SA, Geneva, Switzerland

Outline

1. Investigation scope
2. Method and techniques
3. Deployment on 11T dipole coils, Computed Tomography (CT) and Materialographic Analyses
4. MQXF quadrupole coils, local investigations and destructive examinations
 - a. CERN MQXFB coils, extended inspections by deep Copper etching and subsidiary NDT techniques
 - Tested coils (**CR108**)
 - Virgin coils (CR120, CR126)
 - b. Confirmation of the method and investigation of physical quenches on US MQXFA coils:
 - Coil end and wedge/end spacer transitions (**AUP 214**, AUP 213 from non-conforming magnets)
5. Considerations and conclusions

1. Investigation scope

Possible causes of degradation:

- Issues **internal to the coil** – Shear and bending **loads on unsupported wire**
 - Strand / wire is locally supported by the resin system
 - Presence of strands dislocation (pop-in/pop-out)?
- Occurrence of cracks in filaments
 - Extent and severity of possible flaws
- Insulation imperfections, lack of bonding, shrinkage cavities, cracks

2. Method and techniques

Experimental procedure

1. Global, High Energy Linac X-ray Computed Tomography (CT) to identify possible events in a NDT manner in the whole volume at the mesoscopic level
2. Identification of Volumes Of Interest (VOI)
3. Definition of a removal plan and cutting route
4. Localized, High Resolution in-house X-ray Computed Tomography of selected VOI for detail localization
5. Microscopical analysis and destructive tests (DT)



↑ Short model 11 T dipole coil C122 (coil head), connection side

Samples issued from the 4.2 m long AUP 213 coil of the MQXFA08 magnet ↓



MQXFB CR108, 7.281 m long – in 2017 longest Nb_3Sn coils fabricated so far for accelerator magnets ↑


F. Lackner et al., IEEE Trans. Applied Superconductivity, vol. 28 (2018) 1-5

Front view
1:7


2. Method and techniques, NDT

⇓ 6 MeV Linac CT - TEC-Eurolab Modena /IT on a Diondo device, then Diondo GmbH /DE

Resolution: 120 μm
 Spot size: 2 mm
 Energy: 6 MeV



- Microfocus X-ray tube:
 - Max. voltage 225 kV
 - Max. current 3000 μA
 - Max power 500 W
 - Min. focal spot size 7 μm
- High resolution flat panel:
 - 40 x 40 cm
 - 2048 x 2048 pixels, 16 bit
- Tube-detector distance: 1375 mm
- Max. spatial resolution: 4 μm



X-Ray Source	3 / 6 / 9 [MeV]
Detector	Flat Panel Detector 3.000 x 3.000 px, 140 [μm]
Scan Volume, maximum	\varnothing 700 x 1000 H [mm]
Focus-Detector-Distance	4000 [mm]
Sample Weight	200 [kg]
System Dimensions	L 5.900 x B 1.500 x H 2.900 [mm]
System Weight	17 [t]
Manipulation	granite based, 6 / 7 axes,




↑ In house Zeiss Metrotom
1500 CT acquired in 2017 ↓



Advanced Examina

ors for the LHC

2. Method and techniques, DT



↑ Diamond WireTec /DE saw DW.350-L for high precision cutting (DWS)


Advanced material investigation facilities, see [EN-MME-MM](#) ⇒:

- sample preparation (grinding and polishing)
- microscopy observation (optical microscopy, advanced high resolution electron microscopy including FIB, local strain mapping using EBSD technique, quantification of crack distribution)
- Micro- (soon nano-) hardness, mechanical testing


Deep copper etching based on ASTM E340 50% HNO₃ macroetching for Cu and brasses



On polished or as cut and ground surfaces



Hardness testing



Preparation



Microoptical observation



Advanced electron microscopy including FIB-SEM and a wide range of detectors (EDS, EBSD, low voltage EDS)

3. Deployment on 11T dipole coils, CT and Materialographic Analyses

Magnet P1 – Hybrid assembly


Collared Coils: Aperture D1: CC01, Coils: GE02_Upper and GE03_Lower **dismounted in May 2019**

coil GE02 (limiting coil of 1st hybrid assembly)


- **coil02 NCS (GE02)**
- **coil02 CS (GEC02)**

Suspected causes of degradation:

- Locations of concern, like between inner / outer layer, and at the interface between the turns and the head spacers
- Most probably origin of the quench in the inner layer close to the coil pole




11T section



3. Deployment on 11T dipole coils, CT and Materialographic Analyses

Coil GEC02

Coil head connection side
Likely with damages – Quenches
Received in September 2020



Coil GE02

Coil head non-connection side
Supposedly w/o damages – No quench,
Received in July 2020 for NDT feasibility test




Coil GE11

Coil head connection side
virgin state
Received in February 2021




3. 11T, CT Analyses

Coil GEC02 – CT: quenches localized on this side






3. 11T, CT Analyses

Coil GE02 – CT: No quenches localized on this side, no significant events



3. 11T, CT Analyses


Coil GE02 – CT: No quenches localized on this side, no significant events






3. 11T, CT Analyses

Coil GEC02 – Events

Event 1 – first end cable in inner layer,
Misaligned strands
(pop-in / pop-out)





Event 2 – vicinity of fourth spacer in inner layer,
Bulged cable









3. 11T, CT Analyses

Coil GEC02 – Event 1



3. 11T, CT Analyses




Wound but unreacted coil GE27 CS (left),
 virgin coil GE11 CS (middle), limiting coil
 GE02 CS (right)
 Most severe imperfections in the central
 portion near the winding key.

I. Aviles Santillana, S. Sgobba et al.,
Advanced Examination of Nb₃Sn Coils..., to
 be submitted to Superconductor Science
 and Technology


Comparison of the same region with
 imperfections in six connection side dipole
 coil heads

3. 11T, (& MQXF) CT Analyses - Comparison of coil end status (bulged and popped in/out strands)


AUP P06 NCS, internal layer



MQXF 107 NCS, internal layer




MQXF 108 NCS, internal layer



3. 11T, (& MQXF) CT Analyses - Comparison of coil end status (bulged and popped in/out strands)

AUP 214 NCS, internal layer AUP 108 NCS, internal layer




Linac CT of coil heads:

- Allows identifying VOI affected by bulging and popped in/out strand events
- Thorough comparison of the outcome of winding
- Indispensable prior to metallographic cuts at coil heads


3. Deployment on 11T, Materialographic Analyses



Diamond wire
saw cutting
illustrations
300 m of diamond
wire and 6 days
for all cuts



3. 11T, Materialographic Analyses



Volumes of interest have been extracted
316L stainless steel spacer parts detached
from the extracted volumes as a result of
the cutting







Metallography GEC02 – Event 1

Extremity straight cut, mirror to the detached portion, reveals in as-cut state:

- Lack of bonding between cable of interest, spacers and insulation is highlighted at the mirror cut in correspondence of the detached portion,
- Environment of the cable of interest is preserved on this cut and has been studied

Polished surface of the present cut allowed to show that:


- Pop-out/pop-in strands are embedded in resin
- SC appear free from cracks in this position
- Cracks in insulation and porosities can be observed, especially at the vicinity of spacers
- Copper composing the strands is at annealed state (approx. 55-60 HV0.1)







Metallography GEC02 – Event 1

Cable of interest detailed examination shows:







- The presence of angular and radial cracks at indicated plane (few SC impacted from pop-out and other strands of the cable)
- SEM-EDS confirmed that phases in presence in sub-elements composing the SC are the one expected after reaction
- Pop-out/pop-in strands are embedded in resin (some porosities are observed)
- Copper composing the strands is in annealed state (approx. 55-60 HV0.1)




Filaments (belonging to different strands) are affected by cracks in the SC phase




3. 11T, Extension in axial direction of radial cracks, assessed by FIB-SEM (C122 coil)



Crack 2






3. 11T, FIB-SEM (C122 coil)



Morphology of crack 1, 22.7 μm deep

Crack 2, phases analysed by EDS, presence of Nb, Sn and traces of Cu




4. MQXF quadrupole coils, local investigations and destructive examinations - MQXFB CR108


MQXFBP1, CR108:

- Limiting coil of MQXFBP1 at 15 kA (6.5 TeV equiv.)
- Very reproducible quench
- Performance loss at 4.5 K consistent with 1.9 K behaviour (no reverse behaviour), reproducible after thermal cycle
- Quench location A 140~235 mm from the mechanical centre of the magnet



MQXFB prototype performance (F. Mangiarotti, S. Izquierdo Bermudez et al.) ⇒





MQXF section ⇒



Quench location A: 3127-3118




Quench location B: 3113-3126



Courtesy F. Mangiarotti, "Central sample from MQXFB coil CR108", <https://indico.cern.ch/event/1034788/>

Quench position (MQXFBP1)



Franco J. Mangiarotti

Front view 1:7


4. MQXFB CR108, CT

CT of straight part segment **CR108LJ** and CR108OLJ




Outcome of CT:

- Absence of bulging and popped in/out strands in straight sections
- Precise dimensional position of references (holes in the Ti-alloy pole) before cut (dimensional metrology tool)




Straight part segment CR108LJ - REFERENCES





4. MQXFB CR108, CT

CT of straight part segment **CR108LJ** and CR108OLJ




Outcome of CT:

- Absence of bulging and popped in/out strands in straight sections
- Precise dimensional position of references (holes in the Ti-alloy pole) before cut (dimensional metrology tool)
- **For the first time, identification through CT of severe cracking in the resin reach areas of Ti alloy pole shims, eventually confirmed by metallography**





4. MQXFB CR108, DT


Metallographic examination – planes of interest



- ★ Quench location A
- ★ Quench location B





Dashed lines indicating the planes prepared and examined in cross-section: 1, 2, 3a, 3b and 4



4. MQXFB CR108, DT – cross sectional cuts

Example of Cut 4: a thorough examination revealed the presence of micro cracks at SC phase (14 sub-elements for sector A, 85 for sector B and 47 for sector D) that seem to be mainly located in a cloud (stress field?). Only few events (<5) with random location have been identified on C.


🔴 Conductor exhibiting micro-cracks (several sub-elements can be impacted for an indicated location)




4. MQXFB CR108, DT – deep copper etching

Protocol

Planes previously polished and examined are progressively attacked with HNO_3 diluted at 50% in water (ASTM E340 macroetching) with optical examination between each step. Approx. 400 μm to 600 μm of copper are etched out by this mean.



General view of the transverse cross section after etching, example of cut 4




General view of an etched strand, example of cut 4

4. MQXFB CR108, DT – deep copper etching



Several thorough examinations of the whole transverse cross sections between copper dissolution steps and after the last step revealed for cuts #1, #2 and #4 that:

The same and the only one strand at the top edge of the Rutherford cable adjacent to the pole block at inner layer exhibits collapsed SC filaments. The portion of the affected strand where filaments are broken is consistent in the three cuts. Cut 3b does not exhibit broken filaments.





4. MQXFB CR108, DT – deep copper etching , SEM examination

SEM examination allows collapsed filaments and fractured SC sub-elements to be highlighted. Some filaments are missing, they probably withdrew in rinsing water after etching.






4. MQXFB CR108, DT – deep copper etching , SEM examination

Some filaments are missing (probably withdrew in rinsing water after etching); filaments that seem still intact: 75/108, 76/108, 74/108 for cut 1, 2, 4, respectively.



4. MQXFB CR108, DT – deep copper etching , SEM examination



Highlight on fractured filament exhibiting transverse plane fracture: the fractured surface appears perpendicular to filament axis with a typical aspect of a brittle fracture



4. MQXFB CR108, DT – longitudinal cuts

Extraction of the VOI



Extraction of the VOI containing the cables at pole block inner layer has been carried out by DWS.



4. MQXFB CR108, DT – longitudinal cuts

Optical examination


Progressive polishing with intermediate observation steps has been performed to access to 1st and 2nd row's midplane of the first Rutherford cable. The 1st row's midplane exhibits events at superconductive filaments.



2nd row's midplane

4. MQXFB CR108, longitudinal cuts – quench location A (LJ)


Optical examination – 1st row's midplane



Examination of the whole surface reveals large cracks with clearly cracked filaments in several strands at the top edge of the Rutherford cable close to titanium poles.

Opened and cracked filaments seem to exhibit a V shape which could indicate bending issue.

4. MQXFB CR108, extended inspection by deep copper etching



- Reminder of further steps envisaged for coil CR108
- Assessment of large volumes through DWS cutting followed by light grinding and deep Copper etching
- **2 x 1 m coil lengths** to be explored symmetrically around A & B quench locations
- **2 x 20 slices x (20 h – cutting + 4 h - etching and examination) = 320 h (40 d / 8 w) + 560 h as background task**
- tbc based on first examined samples

Analysis type	Performed by	Cutting Date	Analysis Date	Longitudinal position (Distance from LE end, mm)	Results
Tomography&Metallography	EN/MME/MM	Oct-20	Dec-21	150-450	CERN-0000218257
Image Analysis	TE/MS/LMF	Oct-20	Feb-21	450-500	EDMS 2479219
Mechanical	FNAL	Apr-21	Sep-21	640-740	
Mechanical	FNAL	Apr-21	Sep-21	740-840	
Heat Transfer	TE/CRG/CI	Apr-21	Nov-21	840-975	Indico 1147897
Metallography	EN/MME/MM	Oct-20	Jun-21	3460-3860 LJ/OLJ	EDMS 2646593
Tomography	EN/MME/MM	Oct-20	Jan-21	3460-3860 LJ/OLJ	EDMS 2605729
Metallography	TE/MS/SCD	Nov-21	ongoing	4750-4800	
Metallography	TE/MS/SCD	Nov-21	ongoing	4800-4850	
Metallography	EN/MME/MM	Mar-22	Apr-22	6540-6580	indico 1145267
Metallography	EN/MME/MM	Mar-22	Apr-22	6580-6620	Indico 1145267
Mechanical	FNAL	Apr-21	Sep-21	6781-6881	
Mechanical	FNAL	Apr-21	Sep-21	6881-6981	
Tomography&Metallography	EN/MME/MM	Oct-20	Dec-21	7181-7481	EDMS 2605746


Courtesy S. Izquierdo, further details, see: <https://indico.cern.ch/event/1145267/>



4. Extended inspection by deep copper etching: MQXFB CR108, [EDMS 2731361](#)

Results – 3750-4750 ↓

Sketches not at scale








★ No events observed

★ Strand(s) with collapsed filaments

Three positions 300 mm, 650 mm and 700 mm from quench region exhibit damaged strand

4. Extended inspection by deep copper etching: MQXFB CR108, EDMS 2731361

Results – 3750-4750 ↓



★ No events observed


★ Strand(s) with collapsed filaments

4. Extended inspection by deep copper etching: MQXFB CR108, [EDMS 2731361](#)

Sketches not at scale

pole-to-pole transition

Results – 3750-4750



Observed events are in correspondence to titanium pole ends


4. Extended inspection by deep copper etching: MQXFB CR108, [EDMS 2731361](#)

Results – 2460-3460 ↓

Sketches not at scale



LJ



2470 2520 2570 2620 2670 2720 2770 2820 2870 2920 2970 3020 3070 3120 3170 3220 3270 3320 3370 3420


★ No events observed

★ Strand(s) with collapsed filaments




4. Extended inspection by deep copper etching: MQXFB CR108, longitudinal cuts, EDMS 2731361

- Longitudinal cuts of the 108 coil-samples 2670 and 3900 (both presenting crack-events as previously shown)
- The longitudinal cut 2670 was found to have approx. 240 crack-events spread over the longitudinal cross-section, especially close to the region where Cu was previously etched away.

Longitudinal cut 2670 – Cross-section overview



The extent of the events is approx. 20 mm.




4.b MQXFA07 - AUP 214 CS metallurgical inspection, EDMS 2739504


Coil AUP214 from magnet MQXFA07 after initial ramp-up was limited by several quenches below nominal current during training. According to voltage tabs, the portion involved into limiting the performance is located in between turn 2 to turn 6, inner layer, in coil's head at connection side.

Prior NDT on both coil's heads revealed the presence of bulged cables and some popped out strands.


Transverse cross sections covering transitions end spacer and wedge – 1st




Coil 214 – collapsed cable location



Courtesy Giorgio Ambrosio



Power test of MQXFA07 (J. Muratore, S. Feher, G. Ambrosio et al.)






4.b MQXFA07 - AUP 214 CS metallurgical inspection, [EDMS_2739504](#)

1st priority cut - Transition between end spacer and wedge

10 mm thick slice covering the transition between end spacer and wedge.


Two halves have been ground and polished to approach the interface.



4.b MQXFA07 - AUP 214 CS metallurgical inspection, [EDMS 2739504](#)

1st priority cut - Transition between end spacer and wedge

LJ & OLJ side – deep copper etching




Copper dissolution with 50% HNO₃ (according to ASTM E340).

450 μm-600 μm depth has been dissolved




Not a single strand exhibits collapsed filaments.

The same result was found for the OLJ side.



4.b MQXFA07 - AUP 214 CS met

1st priority cut - Transition between end s



Few cracks at midplane block in a delimited area
A localized field of transverse cracks at SC filaments
is observed at pole block

Original high-definition stitched picture are set out in annexes

4.b MQXFA07 - AUP 214 CS metallurgical inspection, EDMS 27

1st priority cut - Transition between end spacer and wedge

OLJ side – longitudinal cut 2nd row




No transverse cracks at SC filaments are observed at pole block 2nd row of Rutherford cable





4.b MQXFA07 - AUP 214 CS metallurgical inspection, EDMS 2739504

1st priority cut - Transition between end spacer and wedge


Field of view of the cut shows that the block and OLJ mid-line and pole block seems to be localized to a certain area on longitudinal cross section






Transverse cracks (with respect to longitudinal axis of the strands) exhibit intergranular fractured aspect.
Networks of secondary cracks are observed

Mag = 13.30 K X Mickael Crouvazier
Aperture Size = 60.00 µm Date: 28 Jun 2022



10 µm EHT = 5.00 kV Width = 127.0 µm Mag = 900 X Mickael Crouvazier
WD = 4.7 mm Height = 95.27 µm Aperture Size = 60.00 µm Date: 28 Jun 2022
Signal A = SE2



100 µm EHT = 5.00 kV Width = 1.143 mm Mag = 100 X Mickael Crouvazier
WD = 4.7 mm Height = 857.2 µm Aperture Size = 60.00 µm Date: 28 Jun 2022
Signal A = SE2

5. Considerations and conclusions

- A sequence of NDT examinations through large volume Linac and local CT of VOI followed by cross-sectional, deep Copper etching and longitudinal observations of cracked filaments allowed to **univocally identify physical events associated to the quenches (broken filaments in strands at specific positions) – previously identified using other tests (e.g. voltage tapes for CR108 coil)**
- The **longitudinal extent of the damage** of the affected Rutherford cables can be assessed through longitudinal cuts following **deep Copper etching**
- Extended and/or severe conductor damage is **almost systematically identified in correspondence of transitions or singularities**:
 - Vicinity of spacers (bulging and popped in/out strand events)
 - Titanium pole ends (broken filaments)
 - End spacers - wedge transitions (large field of cracks)
- Assessment of the resin status is straightforward in cross-sectional cuts
- The applied sequence of NDT + DT examinations **is reconfirmed as a powerful tool to identify conductor imperfections and/or damage of the superconducting phase, and to assess the severity of such damage**



home.cern

3. 11T, (& MQXF) CT Analyses - Comparison of coil end status (bulged and popped in/out strands)


*outer layer of coil MQXFB 120 is not representative (absence of binder)

Name	State	Popped in/out strands events Outer Layer	Popped in/out strands events Inner Layer	EDMS report
MQXFS 106 CS	Limiting MQXFS3c	14	6	2667969
MQXFS 106 NCS	Limiting MQXFS3c	13	5	
MQXFS 107 CS	Reference CERN	2	1	2646366
MQXFS 107 NCS	Reference CERN	0	1	2605746
MQXFB 108 CS	Limiting coil	9	10	2667966
MQXFB 108 NCS	Limiting coil	13	11	2605746
MQXFB 108 Straight	Limiting coil	0	0	2605729 2605732
MQXFB 120 CS	Winding inner layer	(15)*	1	2668915
MQXFB 120 NCS	Winding inner layer	(11)*	1	
AUP_P06 NCS	Reference USA	0	0	2646366
AUP_108 CS	USA- SELVA winding	2	0	2683078
AUP_108 NCS	USA- SELVA winding	5	2	
AUP_214 CS	USA – Limiting coil	3	2	2721396
AUP_214 NCS	USA – Limiting coil	5	2	

4.b MQXFA07 - AUP 214 CS metallurgical inspection, EDMS 2739504


1st priority cut - Transition between end spacer and wedge

LJ side




Some “usual” shrinkage cavities through glass fibres/resin matrix are identified. Ceramic coating on end spacer ensures good cohesion with resin. Inspection of SC filaments did not reveal any major events. Some radial “closed” microcracks can be observed.

For the OLJ side, very similar results were found (here also some cracks through the glass fibres/resin matrix were identified)



4. Extended inspection by deep copper etching of longitudinal cuts 2670 and 3900 : MQXFB CR108, EDMS_2731361





The major events were found at the top part of strand 1 up to strand 7. For strand 3 and 6, the “V” shape was identified.



In this sample, only the pole-to-pole transition at the inner layer was present.



The extent of the events is approx. 20 mm



For the longitudinal cut 3900, an extent of the events of approx. 15 mm was observed at the top part (from strand 1 to strand 6). For this specimen, only few minor events (15-20) were observed over the cross-section, in the region close to the etched side.

4. MQXFB CR108, DT – cracks and stress field


Radial cracks and stress map

- The higher concentration of micro-cracks in the analyzed sections of coil 108 straight section is in IL the mid- plane block (see talk from S. Sgobba)

Courtesy S. Izquierdo Bermudez, <https://indico.cern.ch/event/1150724/> and this conference 1L0r2A-03


Coil 108, coil straight section

Conductor exhibiting micro-cracks (several sub-elements can be impacted for an indicated location)



Remark: In the case of BP1, with a maximum coil stress of 100 MPa at warm after loading, we expect 135 MPa in the pole block after cool down and a maximum of 110 MPa in the mid-plane at 15 kA

After cool down



Powering (16.23 kA)

