


# Electronics Testing Protocol

Sabrina Sacerdoti, for APC

APC - 21/10/2022

# The system



## Flexes:

- testing?
- provide bias requirement
- cable check

## DCem motherboard:

- Fermilab production
- PoF
- bias/first stage amplification

## Laser adapter card

- APC production
- lasers

## Other components:

- \* light tight box
- \* fibers
- \* signal cables

DCDC card:  
- production?  
- configured according to SiPM info

# What needs to be checked

- PoF correct voltage output when loaded, in cold
- DCDC correct voltage output, in cold
  - a DCem boar should be prepared with probes to check as done by Mike
- Laser voltage bias offset (warm=cold)
- Laser “alive” after assembly (warm)
- Read out full board using koheron and oscilloscope (in LAr/cold):
  - Noise level (i.e. no noise from DCDC). Check FFT.
  - Baseline level (i.e. laser not disconnected when frozen)
- After connecting to xARAPUCA (and shielding assembled?):
  - Ideal: put in dark box and power. Check signals → check for shorts!  
(caveat: maybe DCDC bias is not OK in warm)
  - Or: check with multimeter for possible shorts before boxing
- Cable connections → avoid shorts

# Testing of individual components

- Flexes → Italy? US?
  - Somehow tested to check they are ok?
  - Evaluate the required bias voltage of each xARAPUCA asap
- DCDC board → Berkley and Iowa in prod.
  - Configure each board according to LV\_DCDC and the required SiPM BIAS (PICO board is configurable though 45-47V)
  - Check output in LAr with independent power supply
- Laser driver → can be tested at APC
  - Determine expected laser output when powered warm
  - Warm test: check laser output
  - Cold test? To check laser offset? (300mV on S3 and 5V bias)
- DCem → testing at Fermilab?
  - Using copper power, check LDO out (5.1V) and voltage level on S2 (~300mV)
  - Configure jumpers and check for oscillations
  - Power up PoF, check voltage levels: LV\_6V, 5V, LV\_DCDC

# DCem and Laser driver integration

- WARM/copper:
  - Check LDO out
  - Check laser bias offset
  - Check laser power output/koheron
  - Check continuity btw flex and board
- COLD/PoF/DCDC final check:
  - Read out laser signal using Koheron and oscilloscope
  - High enough baseline
  - No oscillations/noise
- Testing facility requirements:
  - LAr
  - PoF lasers
  - 5V and HV power supply
  - Koheron
  - Oscilloscope
  - Function generator?

# Questions - Comments

- Can we trust that if we test one DCDC board for noise, then the others will be OK?
- Can we trust PoF to give consistent output? (or do we need to test all assemblies in LAr?)
- Do we need to test each light shielding box?
- We need to test the tubes! (at least one)
- Testing all boards in LAr: necessary to avoid surprises (bad solders or issues with components, laser)
- All lasers should be checked in LAr. Can be done with just the adapter card.
  
- Where will each testing stage take place?