

# INSTITUTE for RARE ISOTOPE SCIENCE

중이온가속기연구소

**Prototyping of  
Single Spoke Resonators(SSRs)  
for RAON**

**- Hoechun Jung -**

# SSR cavities are on 2<sup>nd</sup> prototyping


	QWR	HWR	SSR1	SSR2
Optimum $\beta$	0.047	0.12	0.3	0.51
$f$ [MHz]	81.25	162.5	325	325
$L_{eff}(= \beta_o \lambda)$ [mm]	173.5	221.5	276.9	470.8
$R/Q$ [ $\Omega$ ]	469	295	233	290
$E_{peak}/E_{acc}$	5.7	5.2	4.1	3.7
$B_{peak}/E_{acc}$ [mT/(MV/m)]	10.4	9.0	6.9	7.7
$E_{peak}$	34.8	34.3	34.9	32.2
$B_{peak}$	63.4	59.4	58.7	67.0
$E_{acc}$ [MV/m]	<b>6.1</b>	<b>6.6</b>	<b>8.5</b>	<b>8.7</b>
$V_{acc}$ [MV]	<b>1.06</b>	<b>1.46</b>	<b>2.35</b>	<b>4.1</b>
Stored Energy [J]	4.7	7.1	11.6	28.3
QRs	18.1	36.8	92.2	112.9

Installed in the SC linac already


Test for 1<sup>st</sup> SSR cavities  
& 2<sup>nd</sup> prototyping is starting  
→ Check & improve  
all designs & processes.

# SSR Development with TRIUMF (Balloon Concept)


Design suggestion (2015. 07)



Test @ TRIUMF (Bare: 2018. 01, Jacketed: 2019.07)



- Cost effective design:  
Just 4 ports, minimized # of stiffeners,  
less fabrication process (forming, welding)
- Narrower multipacting band: < 4MV/m
- But deep drawing for half shell is not easy.  
→ Plan B: Minimum straight + two shells




# Deep Drawing Process for a Half Shell

Depth after pressing

[mm]	SSR1	SSR2
Depth	218	277

Half shell after machining

[mm]	SSR1	SSR2
height	173	243




# Thickness of the Half Shell



Measuring using  
3D laser scanner  
(Hexagon 8535-7)



Measured thickness of a half shell





3.2T 900Φ plate

→ 2.9~3.4T (~10% changed) 500Φ half shell

- Press dies and drawing process are well optimized
- Make balloon shapes successfully

# Tests for 1<sup>st</sup> Prototypes




- ◆ 2 of 4 SSR1 cavities passed the qualification
- One SSR1 cavity is failed with strong field emission
- Another one is failed with thermal quench
- ➔ Will be tested in a cryomodule

- ◆ 6 SSR2 cavities are fabricated
- Stocked about 1~2 years in air, cleanroom after HT baking
- 2 of 6 are tested without additional HT baking & will test again with additional HT baking
- 4 of 6 are tested with additional HT baking
- ➔ Check the process & contamination (foreign materials, particles, gas)

# Checking Frequency: Plastic Deformation during Vacuum

	#4		
	air	vacuum	
1	325.7853		Jacketing
2	325.7329		light BCP
3		325.2665	Cleanroom assembling
4		324.935	After VT
5	325.218		
6		325.1	Cleanroom assembling
7		324.92	After VT
8	325.2678		HT baking
9	325.2547		light BCP
10		324.9955	Cleanroom assembling
11		324.7051	After VT
12	325.1656		HT baking
13	325.1581		light BCP
14		324.8891	Cleanroom assembling
15		324.6696	After VT
16	325.0727		light BCP
17		324.7792	Cleanroom assembling
18		324.6611	After VT
19	325.0199		light BCP
20		324.7557	Cleanroom assembling
21	325.0042		light BCP



Resonant frequencies of 1<sup>st</sup> prototypes are continually decreased  
: Mistake of making vacuum without fixing the beamports

# Holding Jig for Vacuum

Table 10: Stress on cavity and jacket with various conditions at or near room temperature

RF, He, Iso Pressure (bar)	CM situations	Cryostat situations	Lab test situations	Beam Pipe Fixed (MPa)		Beam pipe Free (MPa)	
				Niobium	SS316L	Niobium	SS316L
0, 2, 0	Cavity cooldown	Cavity cooldown		36.9	64.5	34.9	65.7
0, 1, 0	He purge	He purge		18.5	32.2	17.4	32.9
1, 2, 1			pressure test	18.5	32.2	17.4	32.9
1, 0, 1	He - pump			18.5	32.2	17.4	32.9
			He leak chk				
0, 1, 1		RF pump		18.3	negligible	44.8	37.5
			RF leak chk				
1, 1, 0	Isolate leak chk			9.7	33.9	33.1	34.1
0, 0, 1		He, RF-pump		9.7	33.9	33.1	34.1
			RF,He leak chk				



Handling Jig for cleaning process in the vender





Fixing Jig for vacuum !  
Not only for cavity cold Test

- Send this jig to the vender
- Fix beamports for leak test, clean assembly in the vender



# Improved Q Factor with Additional Magnetic Shield



Additional magnetic shield



- Q factor of some SSR cavities at the low gradient is lower than the expectation
- Checked the geomagnetic field in the cryostat(13.6 ~105.6 mG)
- Reduced the geomagnetic field with the additional shield(2.1~ 9.8 mG)
- Decrease of surface resistance is checked with the magnetic shield by  $3n\Omega$

# Thermal Quench





SSR2 #6



Thermal Quench with no or low x-ray  
→ Metallic foreign material  
or metallic particles  
or poor welding  
→ Visual inspection inside the cavity  
: no evidence of foreign materials  
or poor welding  
but particles from the test coupler  
→ Will be tested again after  
light BCP + HPR  
But still worry about foreign materials  
→ Heavy BCP+ HT baking  
if there is no improvement

RF level: Slow rising & Fast falling with amplitude locking

# Contamination: Particle (test coupler)



Thermal quench

→ Visual inspection of cavity & test coupler




→ blowing & check particles

→ **Assembling with cavity when no more particle**


Particles with N2 blowing in Class 10 cleanroom

	0.3um	0.5um	1um
1 <sup>st</sup> blowing	5	3	0
After 3 times	0	0	0

# Reduce grey zone: cavity tilted $\pm 20^\circ$ & Nozzles Optimization



# Contamination : Foreign Material





Nb Plates & Half shells : Dozens of dents and dusts are founded after soaking

→ mechanical & chemical polishing


→ Could not be removed perfectly

→ Need more cleaning before & during the process

in the vender & sub-vender




# Hard Barrier: Multipaction at High Gradient




Multipaction  $\rightarrow$  acceleration  $\rightarrow$  impact  $\rightarrow$  x-ray & secondary electrons

?

# Hard Barrier due to Poor Surface Condition?




## Multipaction of SSR2



High Temperature baking (~600°C) : November, 2021  
Cold Test : September, 2023  
→ Stocked in air, cleanroom  
→ Poor surface condition ?  
➔ 600°C baking & test again ASAP

# Contamination: Gas, Vacuum Spike






A faint, light gray world map is centered in the background of the slide, showing the outlines of continents and countries.

**Thank you  
for your attention**

# Test Failure due to Test Coupler Problem for HWR Mass Production



High failure rate of HWRs qualifying test in early stage

- More than 60% failure
- Damaged surface of test couplers is checked
- After additional rinsing and higher temperature baking failure rate is reduced to around 20%
- Total pass rate with 30mm couplers is less than 70%

More than 90% pass rate with new test couplers

- 12 new test couplers(40mm) are fabricated
- 51 successful cases among 56
- Pass rate is obviously increased.
- There is no evidence for surface damages

