




MICE Spectrometer Solenoid Repair






MICE Spectrometer Solenoids




- These magnets have had a long history and I will make NO attempt to review it in any detail here.
 - Steve and Soren will fill in some of the details
- Both magnets met the full specification at the vendor and were fully mapped.
 - Cryogenic operation was very good. Both magnets had significant cooling headroom (SS2 more than SS1)
- SS2 (in upstream position of the beam line – SSU) has reached full operating current at RAL, but full training (soak, solenoid mode) has not been completed.
- SS1 (in downstream position – SSD) had a lead failure during training.
- What is the optimal path forward?

Reminder: Basic design



- 5 2-stage CCs
- 1 single-stage CC
- 5 Coils
- Max current $\sim 300\text{A}$
- High inductance
10-40H

Power system





Power delivery system



- 2 Vacuum feedthroughs bring power into vacuum space
 - One for ECE, one for M1 and M2
- Copper leads to HTS
 - $IL/A = 3.6 \times 10^6 \text{ A/m}$
- HTS:
 - HTS-110 500A (M1, M2, C) and 250A E1 and E2
- LTS:
 - Vacuum feedthrough: Proprietary Wang design based on SSC superconductor
 - Inside He space: Cu stabilized conductor



Training SSD




- SSD has been a bit problematic at RAL
 - Some vacuum issues
 - Lost voltage tap on LTS lead of M2 coil
- In the training run of September 13th, 2015 all was going very well.
 - Implementation of additional QP for the M2 lead had not yet been done, so a decision was made to ramp only M1 and ECE
 - A quench occurred at $\sim 260\text{A}$ in ECE (much higher than expected, next slide).
- QP system performed as expected, nothing outwardly unusual except for the large current.



Training history



SS1 Training Progress



February 20, 2014

Alan Bross | DOE Review of MAP (FNAL, February 19-20, 2014)

1



Lead failure

- However, upon entering the hall the odor of burnt FR4/G10 was extremely strong. Strongest at He relief valve
- After a great deal of analysis, it has now been determined that (see diagram on next slide):
 - One leg of M1 dead short to ground. This is LTSA lead.
 - LTSA lead not connected to coil (open), but connected to LTSA with $\sim 2.4\text{K}\Omega$ resistance.
 - M2 coil OK.
 - No damage seen anywhere else.
 - However, M2 coil has $1.3\text{K}\Omega$ resistance to M1 (& ground)
 - AC measurements show that QP on M1 not active indicating a break in the internal QP circuit. Most likely point is indicated in the figure on the next slide (x next to diodes) because there is another short to ground on this leg of the circuit.
 - All other coils OK (including their QP circuit).

M1 circuit after fault





Diagram of the M1 circuit. Resistance (four wire and two wire) measurements revealed:

- Lead A has hard short to ground,
- LTSA is shorted to LTSA through 2.4 kOhms and LTSA is not connected to the M1 coil on the Lead B side.



QP data – M1

Quench on September 13th






QP data – M1

Expanded V scale

Quench on September 13th






QP data – M1

Expanded V scale II



Quench on September 13th





Analysis




- Quench initiated on ECE and initially proceeded normally
 - There is no evidence that any LTS leads were involved initially
- At ~ 20 sec, the internal QP for coil M1 failed
 - The voltage on the coil increased rapidly and, it appears that an arc at the LTS power feed through (from vacuum to LHe volume) occurred which burned out the lead and effected M2 (the power leads for M1 and M2 utilize the same 4 pin feed through).
- What caused the QP failure?



Internal QP


Original Wang configuration





We have add previous issues








LBNL re-design

Picture of final configuration for SS2/SSU




Conductively cooled resistors

Quench protection circuitry



SS1/SSD


This is a photo of the QP pack for SSD/SS1. What is not known at this time is exactly how the terminations were made. Did Wang follow the procedures used on SSU/SS1?





Normal Quench

Normal quench event
Contactor opened



- These are data from a normal quench
 - All coils ramping together to their design current
 - NOTE: In this case, the quench occurred as the currents were ramping down
- ECE initiated the quench (QP system detected and sent trigger to open contactors)
- M2 followed, then M1
 - As predicted.





Quench delay $M1$ & $M2$



SSU spontaneous quenches

ECE magnet quenched






Quench propagation analysis without M2 powered




Case I

Hot Spot Temperature



Case II

Hot Spot temperature



- Compared the results with (case I) and without (case II) M2 powered.
- Quenches were initiated in E2 in both cases.
- The quench current in case I is 265A in all coils.
- In case II, the quench currents in ECE and M1 are 260A and 250A, respectively.



Quench delay

- Time to Q for M1 increased by $\sim 2X$
- However, overall scale in simulation does not agree with data
 - There is a qualitative understanding
 - LHe & gas not modeled exactly
 - The thermal properties of the mandrel + insulation between coils and the bobbin are not precisely known
 - The starting location of the quench will affect the heat propagation from the hot spot to the mandrel, this will cause time difference. The model is always set so that the innermost layer initiates the quench.
- Given the above, there is qualitative agreement:
 - The quench delay of M1 increased by $\sim 2X$, from 10 seconds to 20+ seconds.



Moving Forward

- Can obtain lattice to allow MICE Step IV running without SSD M1 coil. However, limits momentum scan
- Harder when RF is added
 - Impossible?
- However, risk that a M2 lead will fail must be considered high at this point
 - M2 has been powered at low current (5A) and all looked good.
- Need guidance on how to proceed