




# Yoke load test and box opening







## Foot fixture and yoke installed








# Up up and away










#### Visual inspection



- All protective panels off one side
- Slow inspection behind each panel from the top down
- Everything looks good by eye



# Shipping box put back together



Suspension system enclosed



## Cable tray installed and parked



- Cable tray installed
- Center yoke support installed
- Protective plastic sheathing draped over for trip
- Parked in front of cold box
- Beam connected to cold box
- Test fit/rolled APA into cold box
  - Trolley wheels on kapton
  - Tested for NO continuity between APA frame and beams
- Ready for CE team



