# Neutrino Beamline Prototype Horn A Final Design Review

**Prototyping** 

Cory Crowley / Meredith Lee 27 January 2021









### **Outline**


- Prototyping Approach
- Stripline
- Water Ports
- Instrumentation Connections
- Spider Supports
- Summary

# **Prototyping Approach**


- Focus on high value, high risk elements that carry across all horn designs.
- Approach is graded in order of magnitudes.
  - Test 10K in ceramics before testing 100K+
  - Test 4 water ports before testing 40+
  - Test 1 assembly process & document before testing 10+ more...
- Horn A prototype will test all features at next order of magnitude.
- Results of that effort will provide guidance for 10M+ production horn & stripline block designs. Likely ~50M+ throughout entire operational lifetime of facility.


# **Stripline Prototyping – PDR Refresh**


- NuMI design unusable for 5kV.
- Had to switch to self-centering ceramics but stuck with PSZ-MGO for resilience.
- Bolt upsized to ½-13 to guarantee "swaging" of tapered ceramic interface concept to bus before face-to-face hard stop.
- External ceramic provides centering of bolt group.
- Metallic spacer on opposite side ties hardware to voltage potential.
- No electrically floating hardware.




# **Initial Concept: E-Fields & Fitment**








# **Prototyping Plan at PDR**



# **Started Assembling!**


- All parts arrived at specifications.
- Started checking fitment.
- Looking good...
- Parts swaging...





#### Started to Fail...


- Some swaging stacks did work.
  - Took every bit of bolt preload to close-up.
- Most were failures
  - Crooked seating when starting swage process / never re-aligned.
  - Major gaps present.
  - Yielded bolts...
- If unable to work with 100% parts in test environment, will never work in field with 100X connections to make & greater variability.
- Did not proceed to electrical testing.





#### From the Ashes...

- Rely on ceramic chamfer to self-center.
- Lightly broke edge for no cuts.
- Eliminated swage fit & custom tooling needs described in PDR.
- Maintain:
  - 45 degree fitment with ceramic for field stress concerns.
  - No possibility of small gap & no use of radii.
  - They fail entirely in supporting analysis.
- We understand stress riser increases on the hole edge.
- The stress riser at the end of ceramic circumference compressive pre-load is what highly dominates fatigue safety factor.




# **Initial Test Setup & Readout**

- Reassembly of modified components was successful.
- Attempted a few different combinations & always pulled together with little preload.
- Transferred to corona testing cage & hooked up to equipment per EE support direction.
- EE support completed test process & scope interpretation.

Credit: EE Support








# **High Voltage Testing – High Voltage Bolt Groups**

- Trial 1: Test voltage drop (1.6kV) with grounded support blocks & HV bolt groups in place.
- Required: 4.8kV, Results: 6.5kV / Passed

Trial	Background	Inception	Inception	Inception	Extinction	Extinction	Extinction
	Discharge	Voltage	Voltage	Discharge	Voltage	Voltage	Discharge
	[uC]	[kV-rms]	[kV-peak]	[uC]	[kV]	[kV-peak]	[uC]
1	10	4.5	6.4	110	4.0	5.7	10
2	10	4.6	6.5	110	4.1	5.8	10






Trial	Background	Inception	Inception	Inception	Extinction	Extinction	Extinction
	Discharge	Voltage	Voltage	Discharge	Voltage	Voltage	Discharge
	[uC]	[kV]	[kV-peak]	[uC]	[kV]	[kV-peak]	[uC]
3	10	4.6	6.5	110	4.2	5.9	10
4	10	4.6	6.5	110	4.2	5.9	10






- Trial 1: Test HV conductor (5kV) with grounded support blocks.
- Required: 15kV, Results: 19.9kV / Passed


Trial	Background	Max	Max			
	Discharge	Voltage	Voltage	Discharge	Inception	OC Trip
	[uC]	[kV-rms]	[kV-peak]	[pC]		
1	3	11.2	15.8	250	х	
2	3	13.8	19.5	70		х
3	3	12.8	18.1	20-30		х
4	3	14.1	19.9	60		



- Trial 2: Swap out isolators to verify repeatability.
- Required: 15kV, Results: 20.1kV / Passed

Trial	Background	Max	Max			
	Discharge	Voltage	Voltage	Discharge	Inception	OC Trip
	[uC]	[kV-rms]	[kV-peak]	[pC]		
1	3	12.1	17.1	20		х
2	3	14.0	19.8	20		
3	3	14.2	20.1	20		





1.27.21

Trial 3: Test full assembly with grounded through bolts only.

Required: 15kV

Results: 19.7kV / Passed

#### **Credit: EE Support**

Trial	Background	Max	Max			
	Discharge	Voltage	Voltage	Discharge	Inception	OC Trip
	[uC]	[kV-rms]	[kV-peak]	[pC]		
1	3	12.7	18.0	60		х
2	3	13.7	19.4	60		х
3	3	13.9	19.7	60		х



**LBNF** 

 Trial 4: Test outer conductors to grounded component (Stripline) pull-up block / Stripline shield block.

Required: 15kV

Results: 20.2kV / Passed

#### **Credit: EE Support**

Trial	Background	Max	Max			
	Discharge	Voltage	Voltage	Discharge	Inception	OC Trip
	[uC]	[kV-rms]	[kV-peak]	[pC]		
1	3	14.3	20.2	64		Х
2	3	14.3	20.2	60		



1.27.21

 Trial 5: Replicate grounded exterior shield with high voltage bolt groups & isolators in place.

Required: 15kV

Results: 20.1kV / Passed

#### **Credit: EE Support**

Trial	Background	Max	Max			
	Discharge	Voltage	Voltage	Discharge	Inception	OC Trip
	[uC]	[kV-rms]	[kV-peak]	[pC]		
1	3	14.2	20.1	60		



# **Findings Throughout Testing**

- All parts started out 100% to specification.
- Tests required reconfiguring 10+ times due to number of variables to test. Many assembly / re-assembly steps, transport, handling...
- Noticed ceramics started to chip, bore edges started to get nicks / scratches.
- Still passed all tests, including deformation test on next slide.
- Shows design is not overly sensitive to material imperfections.







1.27.21


# **High Voltage Testing – Combined Mechanical / Electrical**


- PDR recommendation: Complete mechanical testing of stripline isolation scheme to replicate real movement.
- We could accommodate building a deformation rig. No resources / time to accommodate full vibration testing & we believe best suited for full structure testing when on test stand. Full scale experimental data is highest value data.

Tested with "GO" gauge (shim) to confirm .0625" deflection per 9" of stripline &

repeated corona test; passed.

Credit: Quinn Peterson & EE Support








# **Vendor Prototypes**

- SDSMT is LBNF partner institution & has advanced friction stir-welding lab (AMP Lab).
- Completed major prototyping & testing exercise to confirm capabilities.
- They have "bid" the work & provide the foundation for our welding cost.
  Estimates.
- SOW in process.
- Vendor spec. developed.







# **Vendor Prototypes**


 Completed comprehensive testing & evaluation that exceeded expectations.






Sample	Yield (KSI)	UTS (KSI)	%EL	Weld Efficiency
6101-T61 Longitudinal	17.9 ± 0.1	23.9 ± 0.1	22.3 ± 0.2	NA
6101-T61 Transverse	17.1 ± 0.0	22.9 ± 0.1	22.9 ± 0.1	NA
FSW20002-6 (Transverse)	11.9 ± 0.3	19.5 ± 0.2	17.4 ± 0.2	85%
FSW20002-7 (Transverse)	11.9 ± 0.1	20.0 ± 0.1	17.7 ± 0.7	87%






# **Horn A Design Prototypes – Water Ports**

- LBNF Horns pursue a revision of port design as compared to NuMI / BNB.
   Different from T2K as well.
- Small footprint, inexpensive, immediate assembly, high pressure rating, & reduced component count.
- Required prototype testing in preparation for design review & to verify resilience of concept.















# **Horn A Design Prototypes – Water Port Testing**









### **New Instrumentation Connection**

- Thermocouple vendor (Omega) changed die-sets on ceramic connectors few years ago.
- NuMI stock out, changeover period from old mounts to new connector required drilling out ceramic holes & eventually plug welding & redrilling mounts.
- We must not repeat.
- RAL likely to use some version of this.








1.27.21

# **Spider Supports**

- PDR recommendation:
- Turn plastic into metal. Done!

**Print Credit: Quinn Peterson** 



### **Build Credit: Meredith Lee** & Clay Leonard




1.27.21

### **Overview**

- Spider support installation and measurement procedure was developed to systematically set preloads and ensure concentricity of conductors
- Procedure is used in conjunction with measurement spreadsheet
- Prototype assembled using procedure and spreadsheet
- Specialized sockets developed and tested during the build



Sockets for spider support installation



Spider support assembly

### **Measurement Spreadsheet**

- Centralized document for all measurements made during spider support installation
- Provides tracking for adjustments

Calculates key quantities including total displacement and

preload


	Initial I	Depth Me	asureme	nt (in.)
Spider Support	h <sub>1</sub>	h <sub>2</sub>	h <sub>3</sub>	$h_4$
С	0.589	0.309	0.89	1.788
Α	0.6	0.3	0.89	1.79
В	0.571	0.309	0.89	1.761


	Quantity							Me	easurem	ent Iterat	on						
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
١	h <sub>4</sub> (in)	1.792	1.8	1.89	1.86	1.818	1.859										
	IC Distance																
	(in) Preload (lb)	8.3	41.5	414.8	290.4	116.1	286.2										
	Troioda (ib)	0.0	11.0	111.0	200.1	110.1	200.2										
	Quantity									ent Iterat							
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
3	h <sub>4</sub> (in)	1.764	1.77	1.781	1.79	1.798	1.809	1.83									
	IC Distance (in)																
	Preload (lb)	12.4	37.3	83.0	120.3	153.5	199.1	286.2									
	Quantity							Me	easurem	ent Iterat	on						
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
,	h <sub>4</sub> (in)	1.786	1.794	1.83	1.815	1.821	1.857										
	IC Distance (in)																
	Preload (lb)	-8.3	24.9	174.2	112.0	136.9	286.2										

Belleville Washer Stackup						Spoke					
Но	orn	Spider Support	Number of Belleville Washers	Single Belleville Washer Spring Rate (lb/in)	Belleville Washer Stack Spring Rate (lb/in)	Elastic Modulus (lb/in²)	Minimum Diameter (in)	l Lenath (in)	Cross-sectional Area (in²)	Spoke spring rate (lb/in)	Total Spring Rate (lb/in)
		Α	6	27750	4625	1.60E+07	0.18	10.125	0.0254	4.02E+04	4148
/	4	В	6	27750	4625	1.60E+07	0.18	10.125	0.0254	4.02E+04	4148
		С	6	27750	4625	1.60E+07	0.18	10.125	0.0254	4.02E+04	4148

# **Spoke Base Hardware Installation**

- Slide the spoke base nuts into the corresponding grooves on the inner conductor
- Position the spoke base over the nuts and torque socket head screws to 51 in-lb each
- Repeat for the remaining 2 spoke bases








Spoke base installed

# Timeserts and Flange Installation


- Install Time-Serts in outer conductor
- Apply light film of WD-40 to flange seal and insert in groove
- Fasten flange and Swagelok fitting weldment for each support
  - Torque screws in alternating star pattern in 25 in-lbs increments
    - Final torque on each screw is 125 in-lbs

Tested both titanium & SS screws. Titanium screws also compressed


remaining .004" flange warp from welding step



Timeserts and seal installed



Flange and hardware installed



Cross section of flange assembly

# **Findings from Weld Process**

- Socket weld was anticipated to create some level of flange warpage.
- Warpage measured to ~.009". Flange essentially becomes Belleville washer.
- Fastening with all preload from SS bolts, seal compresses 100% & flange pulls in .005". Edge measured .004" gap.
- Fastening with all preload from Ti bolts, seal compresses 100% & flange pulls in before final torque spec is achieved.
- Will use Ti bolts so all surfaces are fully seated.
- No plans to change process. Belleville direction is in our favor & adds to fastener elasticity.





# **Spider Support Spoke Insertion**

- Thread a Belleville washer and the base nut onto the spider support rod
- Screw the spider support rod into the spoke base
  - Tighten the nut at the base to 125 in-lb using the base nut socket
- Repeat for the remaining 2 spider supports



Using spoke socket to insert spoke





Using base nut socket to tighten nut

1.27.21

# **Hardware Stackup Assembly & Measurement**

- Using a 3/8" threaded rod, insert the ceramic isolator and hardware stackup from the centering washer to the hex nut
- Use a vise to hold the assembly vertically
- Use a depth micrometer to measure from the top surface of the ceramic isolator to the top of the hex nut. Record as  $h_1$ .





Hardware stackup




Measuring depth in vise

# **Hardware Stackup Install**

- Install the isolator and hardware stackup onto the spider support
- Use a depth mic to measure from the top of the Swagelok fitting to the top of the ceramic isolator, and record as  $h_2$


Measure the height of the measurement gauge and record as  $h_3$ 



Measuring h<sub>2</sub>

# **Setting Initial Hex Nut Position**

- Install the measurement gauge
- Measure from the top of the measurement gauge to the hex nut
  - If the measurement does not match what the spreadsheet calculates for  $h_4$ , use the hex nut socket to adjust its position




	Initial I	Depth Me	asureme	nt (in.)							
Spider Support	h <sub>1</sub>	h <sub>1</sub> h <sub>2</sub> h <sub>3</sub> h <sub>4</sub>									
С	0.589	0.309	0.89	1.788							
Α	0.6	0.3	0.89	1.79							
В	0.571	0.309	0.89	1.761							




Measuring h<sub>4</sub>

# **Measuring Inner Conductor Position**

- Place a depth micrometer over the water port adjacent to the spider support to measure the initial distance to the inner conductor
  - Record its value in the spreadsheet
- Repeat slides 30-33 for the remaining 2 spider supports





Water port location

Distance measurement to inner conductor

# **Setting Preloads**

- For one spider support, tighten the hex nut 1/8 turn (45°) using the hex nut socket while holding the spoke at the top with the spoke socket
  - Use a depth mic to measure  $h_4$  and record
  - Use a depth mic to measure the inner conductor position and record
- Repeat for the other spider supports



Using the hex nut and spoke sockets to tighten hex nut

# **Setting Preloads**

- Continue alternating between the spider supports, incrementally tightening the hex nut 45°
- Stop when the spreadsheet calculates that one spider support reaches a preload of 285 lbs
  - Maximum allowable preload

1.27.21

# **Final Hardware Assembly**

- Insert and tighten 12 point nut to 66 ft-lbs on each spoke
  - Use the 12 point nut socket while holding the hex nut with its socket
- Screw on the top Swagelok fitting on each spider support



Completed spider support assembly

# **Summary**

- Major electrical, mechanical, and process assembly steps that could undergo early-stage prototyping have been completed.
  - Corona tests remain for spider support assembly due to ceramic vendor delivery delay.
  - Ceramic puck design that separates striplines at remote clamp now mimic analyzed design for pucks on 12" wide PS bus. Prototyping expected this year.
  - Our stripline will have these features machined late, just before plating.
- Ceramic materials & design features that represent bulk of cost & complexity have passed all EE support tests & meet all EE support requirements for surface path length, voltage isolation, & electric field stress.
- Drawing packages are updated to reflect tested geometry.
- We are ready for full scale prototype production.

### Questions?