

## NuMI: 9AM Meeting

- Tue Nov 29<sup>th</sup>: Ramp card replaced for QD103: elog[228749](#), elog[228762](#), elog[228778](#) & elog[228850](#)
  - Thanks to controls
- Tue Nov 29<sup>th</sup>: TSD took advantage of down day to do maintenance work
- Tue Nov 29<sup>th</sup>: Replaced digitizer for a button BPM
- Wed Nov 30<sup>th</sup>: TSD made an access (beam off) to resolve differential pressure issue: elog[228935](#) & elog[228958](#)
  - Repaired a cracked hose & replaced filters
  - Thank you to TSD for staying late and finishing the work
- Wed Nov 30<sup>th</sup>: Replaced crate for a button BPM
  - Thanks to instrumentation
- Up Next: Implementing a long-term solution for updating permit
  - Try tightening current windows on all correctors
  - Thanks to EE Support for working with us on developing a solution