

BNB: 9AM Meeting

- Tue Jan 3rd: Minor temperature issues when there was MI10 temp controller problem: elog[230981](#) & elog[231036](#)
 - Thanks to Controls & Ops
- Thu Jan 5th: Replaced MI12-B Sump level sensor: elog[231121](#)
 - Was not able to do a simple drop in replacement; thinking about better solutions
 - Looks like the manufacturer may no longer manufacture this model of transducer
 - These transducers are also used for MI12 Well Sumps
 - Thanks to ISD
- Thu Jan 5th: Very small E:H866 current change to get Autotune to behave: elog[231130](#)
 - Tuning last week which led to changes