BNB: 9AM Meeting

- Sun Apr 2nd: ICARUS shifter noted that one of the target BPM readings shifted when the other target BPM reading did not: elog<u>237174</u>
 - This is a know problem with an unknown cause
 - Experts keep working on the problem
- Thu Apr 6th: Some vertical BPM readings were jumping around: elog<u>237534</u>
 - Better behavior after turning off autotune
 - Experts have been made aware of the issue

