

NuMI: 9AM Meeting

- Mon Apr 10th to Fri Apr 14th: Understanding Horn 1 RAW temperature issues: elog[237810](#), elog[237811](#), elog[237853](#), elog[237875](#), elog[237959](#), elog[237983](#), elog[238010](#), elog[238019](#), elog[238020](#), elog[238047](#), elog[238060](#), & elog[238108](#)
 - Experts made a MI65 RAW room access on Wed; made adjustments to water system
 - I will let experts explain what was done
 - We would like to do a beam turn on test
 - Thanks to TSD, MSD, ISD, Controls, Safety, & Ops
- Mon Apr 10th to Fri Apr 14th: V118 magnet bend (E:V118) is causing permit trips: elog[237702](#), elog[237749](#), elog[237775](#), elog[237826](#), elog[237976](#), & elog[238069](#)
 - EE Support studying the issue
 - I will let experts explain the issue
 - Thanks to EE Support & Ops
- Mon Apr 10th & Tue Apr 11th: Reseated & power cycled remote trigger NIM card for NuMI Kicker (I:KPS6N & I:KPS6S): elog[237782](#) & elog[237950](#)
 - Had more Timing Error Unclamp & Seq/Thy Trig Late Error bits bad
 - Thanks to EE Support

NuMI: 9AM Meeting

- Tue Apr 11th: Rebooted NBPMOV frontend due to permit drops: elog[237895](#)
 - Heartbeat signals (60BPMA & 60BPMB) had a clock drift; this is a know issue
- Tue Apr 11th: Swapped a 377 timing card for Muon Monitors: elog[237926](#)
 - Trying to understand stale data issue for Muon Monitors; swap did not help
 - Experts still working on the issue
 - I will let TSD explain
 - Thanks to Controls
- Tue Apr 11th & Wed Apr 12th: Recentered window for V108 magnet bend (E:V108):
elog[237962](#), elog[237993](#), elog[238003](#), & elog[238053](#)
 - Permit drop on V108 going low
 - Thanks to Max