

NuMI: 9AM Meeting

- Sat April 15th: Decay pipe return flow sensor (E:DDRF02) dropped to zero: elog[238327](#)
 - Old sensor; got our money's worth out of it
 - Not easy to replace; ignore it for now
- Mon Apr 17th: to Fri Apr 21st: Monitoring power supply for V118 magnet bend (E:V118):
elog[238311](#), elog[238559](#), & elog[238716](#)
 - V118 power supply is pulling the permit every few days
 - EE Support can elaborate
 - Thanks to EE Support and Ops
- Thu Apr 20th: Restarted tomcat servlet on DCE15: elog[238740](#)
 - NuMI autotune was showing an E:VITGT read error
 - Thanks to Ops
- Want to thank MI for tuning to try to improve baffle temperature issues
 - Larger beam spot size has led to higher baffle temperatures