

BNB: 9AM Meeting

- Tue Apr 18th: BNB fast switch magnet (E:MBEXPS) was tripping off on IPM Faults: elog[238557](#) & elog[238579](#)
 - IPM status comes from a power IGBT
 - EE Support located spare power modules; testing a spare driver card
 - EE Support can give status update
 - Thanks to EE Support
- Thu Apr 20th: Added an alarm to BNB proton rate (E:MBRATE): elog[238732](#) & elog[238741](#)
 - We keep pushing on intensity!
 - Thanks to Ops
- Thu Apr 20th: TSD added water to BNB RAW skid: elog[238753](#)
 - Thanks to TSD