

# TSD report for AD 9 am ops meeting

- **Two days ago, the horn PS was switched from PEI-B to PEI-A. After that, we adjusted the voltage to restore the horn current.**
- **We keep working on fixing muon monitor data quality issue.**
  - ➔ **Jeremy and Dan went down to Minos to observe the blinking light patterns on the Swic scanners to see any TCLK triggering issue. As they reported, all works fine.**
  - ➔ **Phil turned off the sequencer on all monitors except the muon monitor 1 to test any data traffic issues. However, still we see the data quality issue.**