ID	WBS	Task Name	Schedule Finish Date	% Complete	Responsible Institution	Baseline Finish Date	Variance in Working Days
1	1.4.2	T4 - [Ready] - Complete Magnet Warm-up	10/1/15	0%	FN	10/1/15	0
2	1.4.3	T4 - [Required] - Complete Magnet Warm-up	10/7/15	0%	FN	10/7/15	0
3	1.1.4	T4 - [Ready] - Spectrometer Solenoid Technical Review Complete	12/4/15	0%	FN	12/4/15	0
4	1.1.5	T4 - [Required] - Spectrometer Solenoid Technical Review Complete	12/18/15	0%	FN	12/18/15	0
5	1.7.1	T4 - [Start] - Procurement for Magnet Re-assembly	12/18/15	0%	FN	12/18/15	0
6	1.2.2	T4 - [Ready] - Negotiate Design Team	1/22/16	0%	FN	1/22/16	0
7	1.2.8	T4 - [Ready] - SS Recovery Teams in Place	1/22/16	0%	FN	1/22/16	0
8	1.2.3	T4 - [Required] - Negotiate Design Team	2/5/16	0%	FN	2/5/16	0
9	1.2.9	T4 - [Required] - SS Recovery Teams in Place	2/5/16	0%	FN	2/5/16	0
10	1.2.5	T4 - [Ready] - Negotiate Fabrication - Assembly - Testing Teams	3/4/16	0%	FN	3/4/16	0
11	1.2.6	T4 - [Required] - Negotiate Fabrication - Assembly - Testing Teams	3/18/16	0%	FN	3/18/16	0
12	1.2.10	T3 - [Required] - All SS Recovery Teams in Place	3/18/16	0%	FN	3/18/16	0
13	1.3.13	T3 - [Ready] - Complete Technical - Design Review	4/22/16	0%	FN	4/22/16	0
14	1.3.14	T3 - [Required] - Complete Technical - Design Review	5/6/16	0%	FN	5/6/16	0
15	1.3.18	T4 - [Ready] - Complete Vessel - Manufacturing Phase	8/30/16	0%	FN	8/30/16	0
16	1.3.6	T4 - [Ready] - Complete Bobbin - Manufacturing Phase	9/28/16	0%	FN	9/28/16	0
17	1.3.19	T4 - [Required] - Complete Vessel - Manufacturing Phase	9/28/16	0%	FN	9/28/16	0
18	1.3.7	T4 - [Required] - Complete Bobbin - Manufacturing Phase	10/26/16	0%	FN	10/26/16	0
19	1.1.6	T4 - [Conclusion] - Conclusion of MICE Step IV Operations	12/21/16	0%	FN	12/21/16	0
20	1.5.2	T4 - [Ready] - Complete Magnet Warm-up	1/10/17	0%	FN	1/10/17	0
21	1.3.9	T4 - [Ready] - Complete Bobbin - Cold Test	1/12/17	0%	FN	1/12/17	0
22	1.5.3	T4 - [Required] - Complete Magnet Warm-up	1/17/17	0%	FN	1/17/17	0
23	1.5.5	T4 - [Ready] - Complete Preparation to Remove from Beam Line	1/25/17	0%	FN	1/25/17	0
24	1.3.10	T4 - [Required] - Complete Bobbin - Cold Test	2/3/17	0%	FN	2/3/17	0
25	1.5.6	T4 - [Required] - Complete Preparation to Remove from Beam Line	2/6/17	0%	FN	2/6/17	0
26	1.5.8	T4 - [Ready] - Complete Relocation to Repair and Assembly Site	2/15/17	0%	FN	2/15/17	0
27	1.5.9	T4 - [Required] - Complete Relocation to Repair and Assembly Site	2/23/17	0%	FN	2/23/17	0
28	1.3.21	T4 - [Ready] - Complete LHe Vessel - Assembly Phase	3/31/17	0%	FN	3/31/17	0
29	1.6.20	T4 - [Ready] - Complete Magnet Disassembly	4/5/17	0%	FN	4/5/17	0
30	1.3.22	T4 - [Required] - Complete LHe Vessel - Assembly Phase	4/14/17	0%	FN	4/14/17	0
31	1.6.21	T4 - [Required] - Complete Magnet Disassembly	4/20/17	0%	FN	4/20/17	0
32	1.7.38	T4 - [Ready] - Complete Magnet Re-Assembly	7/24/17	0%	FN	7/24/17	0
33	1.7.39	T4 - [Required] - Complete Magnet Re-Assembly	8/30/17	0%	FN	8/30/17	0
34	1.8.2	T4 - [Ready] - Complete Magnet Relocation to MICE Hall	9/21/17	0%	FN	9/21/17	0
35	1.8.3	T4 - [Required] - Complete Magnet Relocation to MICE Hall	9/29/17	0%	FN	9/29/17	0
36	1.8.5	T4 - [Ready] - Complete Magnet Installation on Beam Line	10/27/17	0%	FN	10/27/17	0
37	1.8.6	T4 - [Required] - Complete Magnet Installation on Beam Line	11/8/17	0%	FN	11/8/17	0
38	1.9.2	T4 - [Ready] - Complete Magnet Pump-Down	12/8/17	0%	FN	12/8/17	0
39	1.9.3	T4 - [Required] - Complete Magnet Pump-Down	12/20/17	0%	FN	12/20/17	0
40	1.9.5	T4 - [Ready] - Complete Magnet Cool-Down	1/9/18	0%	FN	1/9/18	0
41	1.9.6	T4 - [Required] - Complete Magnet Cool-Down	1/24/18	0%	FN	1/24/18	0
42	1.9.8	T4 - [Ready] - Complete Magnet Training	2/7/18	0%	FN	2/7/18	0
43	1.9.9	T4 - [Required] - Complete Magnet Training	2/15/18	0%	FN	2/15/18	0