




# SPS MAIN VACUUM CHAMBERS




Bending magnet MBA





Bending magnet MBB



Quadrupole F



Straight sections



Quadrupole D

Fig 2: Vacuum chamber cross sections in the SPS