

Restart of Decommissioning

- Part of Phase-4 of Lab's return-to-work plan
 - Rigging crews and four of electronics disassembly team (Steve H, Howard B, Anne N and Clarence W) to be on access list Jun 11
 - Working to add students/postdocs
 - Aiming next Monday, June 15, to restart electronics disassembly (M6)
- Two crews take turns to go to MINOS hall
 - Next 18 MINERvA modules is to be saved – Howard to confirm
 - Start with 3-day electronics disassembly and 2-day rigging?
 - OR: 2-day electronics and 1-day rigging?
- All need to complete new training class before return to work
 - FN000684 - Working Safely in the Era of COVID-19 and the Return to On-site Work

HA and Procedure Changes for social distancing

- HA 2304 (2320)
 - Add safety glasses as alternative/replacement to face shield
 - Need to complete the HA this week: **Jim, Steve, Angela**, then all team members
- Can we do procedure changes for social distancing?
 - Identify steps of possible getting closer than 6'
 - Pulling cables requires two people to coordinate and likely getting closer
 - Can we do things differently to reduce the chance of needing to be closer?
 - Cutting those cables we have enough spare already?
- Electronics disassembly has the most chance to get worker closer
 - HA2320 modification?
 - Take another look of Clarence's procedure slides?
- Examine process of module disassembly at MSB to avoid getting closer?
 - ~40 more trackers need to be taken apart at MSB

PPE Requirement and Other Protections

- ESH 5518: COVID-19 ES&H Information and Requirements
- Face covering is required all the time in MINOS
 - Face mask available from lab entry gate
 - We also ordered masks -- should be delivered to MSB
- At underground, wear hard hat
 - Nitrile gloves AND safety glasses or goggle (available – check delivery)
 - Or nitrile gloves AND face shield (available – check delivery)
- Wash your hands, clean shared tools frequently
 - Hand sanitizer station in MINOS
 - Alcohol spray bottles for disinfection of shared tools
- MINOS shaft elevator single person ride policy
 - First/last person enter/leave wait for 2nd person on the elevator
- Call MCR (x3721) first before getting keys
 - Can we get OPS group keys?

Fermilab COVID-19 Protective Equipment and Behavior Risk Chart

Potential Exposure Activity	Risk Category	Protective Equipment Requirements	Additional Requirements
Outdoors, separated from other personnel	0	None	<ul style="list-style-type: none"> Maintain a 6 foot or greater social distance.
Inside buildings or enclosures, other common spaces (e.g. elevators, lunchrooms, hallways, vehicles)	1	Face covering (not required to be worn when alone in your personal office/cubical space)	<ul style="list-style-type: none"> Maintain a 6 foot or greater social distance when possible. Respect the capacity limitations for elevators (posted next to elevator car) and restrooms. Limit of two individuals in a vehicle. Clean surfaces used prior to leaving. Wash/sanitize hands after touching surfaces or removing face covering.
Working within 6 feet of another individual	2	<ul style="list-style-type: none"> Face covering and face shield and impervious gloves OR <ul style="list-style-type: none"> Face covering and safety glasses/goggles and impervious gloves 	<ul style="list-style-type: none"> Approved written hazard analysis describing the task, hazards, and protective measures. Wash hands after removing protective equipment.

NOTE 1: "Face covering" means cloth face mask or disposable face mask.

NOTE 2: Medical and first response personnel are to follow their exposure control protocol.

Contact your supervisor or DSO with questions regarding this chart.

