Fermilab Permit Type General Radiological Work Permit No. AD-22-059 **Issue Date** Jan 26, 2022 Tevatron F-Sector **Issue Time** 11:08 AM **Expiration Date** Jan 31, 2023 **Description of Work** Access Type All work, tours, and inspections **EXCEPT FOR**: O Controlled Access 1. Cutting, drilling, or grinding on radioactive material Supervised Access 2. Work in areas posted as High Radiation and/or Contamination areas O Open Access 3. Work on beam pipes and magnet interface areas. See "Special Other - Secured Area Requirements." ONA**Additional Work Area Conditions Basic Work Area Conditions Area Posting** See Enclosure Hazards Radiation Area Specification Sheet **Time Limits Dose Limits Work Documents** None 100 mrem per week and Job-specific HAs as applicable, see 1500 mrem per year are supervisor or DSO administrative control limits **Dosimetry Requirements Other Training Requirements Basic Training Requirements** ☐ None Required Radiological Worker ■ Dosimetry Badge ▼ Pocket Dosimeter ☐ Ring Badge □ Digidose ☐ See Special Requirements **Portable Survey Instruments Minimum Personal Protective Equipment Additional Instructions** None Required None Required ☐ Notify ESH&Q Prior to Work LSM Gloves ☐ Rad Tech Coverage Required Ludlum 14C ☐ Shoecovers Review Survey Map ☐ E140N/Portable Frisker Labcoats ☐ Pre-Job Briefing ☐ Minimeter Personal Frisk on Exit ☐ Coveralls ☐ Hood Survey & Label Materials on Exit ☐ Teletector ☐ Bicron Analyst ☐ Eye Protection ☐ Post-Job De-Briefing ☐ See Special Requirements ☐ Respiratory Protection No Eating, Drinking, Smoking ☐ See attached instructions See Special Requirements SPECIAL REQUIREMENTS ☐ See special requirements Contact MCR to request RSO approval prior to working in any posted High Radiation (100 mrem/hr or greater) and/or Contamination Areas. There is always a potential for contamination on beampipes and in magnet interface areas, therefore before removing any material from such areas, contact Radiation Safety for additional guidance. Ben husself **RSO Authorization** Prepared By Ben Russell



DATE: 46/20 TIME: 0730 PURPOSE Opening up Survey RWP # 80-22-059

This Survey is part of the F-Sector survey package. See attached cover sheet for surveyor, instrument, and review information.

F-SECTOR COVER SHEET

Updated 6/13/19

MAPS INCLUDED

F-0 SOUTH END

F-0 NORTH END

F- SECTOR MAP 1

F-SECTOR MAP 2

F-SECTOR MAP 3

F-SECTOR MAP 4

F-SECTOR MAP 5


F-SECTOR MAP 6

			86	ec 1.47 1	=17 pph	
Beam Off Date: 4-6-22 Be	am Off Time: 0600			20 3,06		Highest Dose Rate Found: 20 mR/hr @ 1foot
Radiation Instruments Use	ed		, 30		Comments:	
Inst Type: USM FIELD		Bkg	d_ <u>50_</u>	cpm	Comments.	•
Inst No: 77 61		Wipe = Reading	Wipe #	Reading		
Batt/Source Chk: SAT/SAT NA/SA		1 0	ccpm	ccpm		
Cal. Due Date: Ap(-) Jon - 2	<u> </u>		ссрт	ссрт		
All Areas < mR/hr@1foot (Unless ot	herwise indicated)		серт	ccpm		
LEGEND: Numbers appearing on map are mR/hi	r @ 1 ft readings unless		серт	ccpm		
denoted with symbols below. * = mR/hr @ contac	t		серт	ccpm	Surveyed By	y: Fulcham/ Make-Start 1807
A = Air Sample $\#$ = Wipe \boxed{F}	= Floor wipe		cepin	ccpin	Reviewed B	y: million



DATE:	TIME:	RWP#

FØ-SOUTH END




Beam Off Date:	Beam Off Time:	. "	Intensity:			Highest Dose Rate Found: 45	mR/hr @ 1foot
Radiation Instruments	s Used				Comments		
Inst Type: Inst No: Batt/Source Chk: Cal. Due Date:		·		Reading ccpm	Comments	•	
All Areas < mR/hr@1foot (Unle		ccpm	ccpm				
LEGEND: Numbers appearing on map are a		серт	ccpm				
denoted with symbols below. * = mR/hr @ co	ontact		серт	ccpm	Surveyed B	y:	
A = Air Sample # = Wipe	F# = Floor wipe		ccpm	ccpm	Reviewed E	By:	



DATE:	TIME:	PURPOSE:	RWP #


F Ø - NORTH END



Beam Off Date:	Beam Off Time:		Inte	nsity:			Highest Dose Rate Found: 15	mR/hr @ 1foot
Radiation Instru	nents Used			,		Comments		
Inst Type: Inst No: Batt/Source Chk: Cal. Due Date:		Wipe # F	Bkgd Reading ccpm	Wipe #	Reading ccpin	Comments	•	
		┧	ccpm		ccpm			
All Areas < mR/hr@1foot ()	Uniess otherwise indicated)	↓	ccpm		ccpm			
LEGEND: Numbers appearing on map are mR/hr @ 1 ft readings unless			ccpm		ссрт			
denoted with symbols below. * = mR/hr @ contact			ccpm		ccpm	Surveyed B	y:	
A = Air Sample # = Wip	be $F^{\#}$ = Floor wipe		ccpm		ccpm	Reviewed E	By:	



DATE:	TIME:	PURPOSE:	RWP #




Beam Off Date:	Beam Off Time:		Intensity:			Highest Dose Rate Found: 20	mR/hr @ 1foot
Radiation Instrument	s Used		2 -		Comments		
Inst Type:		Bkgo	1 30	cpm	Comments	•	
Inst No:		Wipe = Reading	Wipe =	Reading			
Batt/Source Chk:		<u> </u>	ccpm	ccpm	de en company		
Cal. Due Date.		l	ссрт	ccpm			
All Areas < mR/hr@1foot (Unle	ss otherwise indicated)		серт	cepm			
LEGEND: Numbers appearing on map are i	mR/hr @ 1 ft readings unless	l	ссріп	ccpm			
denoted with symbols below. *= mR/hr @ co	ontact	l	ccpm	ccpm	Surveyed B	y:	
A = Air Sample # = Wipe	$F^{\#}$ = Floor wipe		ccpm	ccpm	Reviewed E	By:	



······································		
<u> </u>		
DATE: TIME:	I PI IRPOSE:	RWP #
DITTE.	TORTOSE.	11(4)1 #

Reviewed By:

F- SECTOR MAP 2



ccpm

A = Air Sample


(#) = Wipe

 $(F^{\#})$ = Floor wipe



	7		
DATE:	TIME:	PURPOSE:	RWP #

F- SECTOR MAP 3




Beam Off Date:	Beam Off Time:		Inte	ensity:			Highest Dose Rate Found: _ と S	mR/hr @ 1foot
Radiation Instruments	s Used					Comments	•	
Inst Type:Inst No:			Bkgd		cpm	Comment	·	
Batt/Source Chk:		Wipe =	ccpm	1	Reading ccpm			
All Areas < 5 mR/hr@1foot (Unles	ss otherwise indicated)	 —	ccpm		ccpm			
LEGEND: Numbers appearing on map are mR/hr @ 1 ft readings unless			ccpm	***************************************	ccpm			
denoted with symbols below. *= mR/hr @ contact			ссри		ccpm	Surveyed B	y:	
A = Air Sample # = Wipe	$F^{\#}$ = Floor wipe		ccpm		ccpm	Reviewed I	Ву:	



DATE:	TIME:	PURPOSE:	RWP#

Reviewed By:




A = Air Sample

(#) = Wipe

= Floor wipe



			· · · · · · · · · · · · · · · · · · ·
DATE:	TIME:	PURPOSE.	DIAID #
DATE.	THVIE.	PURPOSE:	RWP#




Beam Off Date:	Beam Off Time:	Intensity:				Highest Dose Rate Found:_	<u> </u>	mR/hr @ 1foot		
Radiation Instruments Used						Comments	•			
Inst Type: Inst No: Batt/Source Chk: Cal. Due Date:		Wipe #	Bkgd Reading ccpm ccpm	Wîpe =		cpm	Comments	•		
All Areas < mR/hr@1foot (Unless otherwise indicated)			ccpm		co	epm				
LEGEND: Numbers appearing on map are mR/hr @ 1 ft readings unless			ccpm		co	cpm				
denoted with symbols below. * = mR/hr @ contact			ссрт		co	epm	Surveyed B	y:		
A = Air Sample $\#$ = Wipe	F = Floor wipe		ccpm		co	cpm	Reviewed I	Ву:		



1				
	~ . ~ ~		TT TT TT C C TT	
1	DATE:	ITIME:	PURPOSE:	IRWP#
1				=

F- SECTOR MAP 6



Beam Off Date:	Beam Off Time:		Intensity			Highest Dose Rate Found: 45 m	R/hr @ 1foot
Radiation Instrument				Comments	Comments:		
Inst Type:		Bkgc	d cpm		Comments	•	
Inst No: Batt/Source Chk:		Wipe # Reading	Wipe	# Reading			
Cal. Due Date:		l — —		ccpm			
Car. Due Date.			ссрт	ccpm			
All Areas < 5 mR/hr@1foot (Unle		ссрт	ccpm				
LEGEND: Numbers appearing on map are		серт	ccpm				
denoted with symbols below. *= mR/hr @ c		ссрт	ccpm	Surveyed B	y:	·····	
A = Air Sample # = Wipe	$(F^{\#})$ = Floor wipe		ссрт	ccpm	Reviewed I	3y:	