

Managed by Fermi Research Alliance, LLC for the U.S Department of Energy Office of Science

Main Injector Operations Status


Osama Mohsen

Weekly meetings

03/03/23




NuMI Beam






Muon Beam






Switchyard Beam






Downtime Main Injector



Main Injector Downtime



Downtime Main Recycler



Recycler Downtime



Other issues

- Recycler RF station 2 is doing better. RF would like to connect station 1 back and tune it so we have a spare.
- RRXDMP (Recycler Ring Transverse Damper) node is not responding. The damper is working but we cannot rephase it or reconfigure it to reduce losses.



Requests

• Studies: \$E1 and \$E0 studies

