

NuMI: 9AM Meeting

- Mon Mar 27th to Fri Mar 31st: Baffle temperature issues: [elog236596](#)
 - Increased beam spot size on target; now easier to put more beam into the baffle
 - Experts are thinking about the issue
- Mon Mar 27th to Thu Mar 30th: Target RAW temperature issues: [elog236584](#), [elog236671](#), & [elog236870](#)
 - Adjustments were made to the PLC system
 - Thanks to Controls, MSD, & TSD
- Mon Mar 27th to Fri Mar 31st: Horn RAW temperature issues: [elog236584](#), [elog236641](#), [elog236912](#), [elog236945](#), & [elog236965](#)
 - Experts are continuing to look at the problem
- Sun Mar 26th to Mon Mar 27th: Kicker (I:KPS6N) repair work: [elog236528](#) & [elog236546](#)
 - Thanks to EE Support
- Wed Mar 29th: Work on absorber pressure sensors: [elog236807](#)
 - Bypass one of the sensors for now (E:ABRP13)
 - Thanks to Controls, MSD, & Ops

NuMI: 9AM Meeting

- Wed Mar 29th: MINOS rack work was finished: elog[236714](#), elog[236748](#), & elog[236807](#)
- Thu Mar 30th: Restored SWIC & timer settings for the 5 downstream monitors: elog[236896](#)
 - Thanks to Max