

TSD report for AD 9 am ops meeting

- **Monday, Katsuya did the second NuMI beam position adjustment (0.2 mm to right) and also adjusted the autotune parameters. We will monitor the baffle temperature with the high power beam operations.**
- **There is a horn1 RAW temperature fluctuation issue.**
 - » **The temperature fluctuates sharply with instantaneous on/off of the beam.**
 - » **We are still trying to understand the reasons for this temperature behavior. Des is carrying out some studies.**