‡ Fermilab

Managed by Fermi Research Alliance, LLC for the U.S Department of Energy Office of Science

Main Injector Operations Status

Osama Mohsen

Weekly meetings

02/06/23



- For the RR, regulator chassis which had an internal LCW leak was replaced at MI-30.
- Beam in RR and MI is available to users once requested.



Requests

• Studies: \$E1 and \$E0 studies

