





FD2 Dichroic/Neutral Filters workflow

PhCollector WG Meeting
C.M. Cattadori
11/06/2024

Substrates (NF) /DF Production




Auxiliary workflows: Glass Substrates Transport Boxes



Procedures t.b.d.

1. Substrates cleaning at ZAOT/PE:
2. Substrates Shipment:
 - a. ZAOT: 24 units vacuum bags
 - b. PE: 24 units vacuum bags
3. Transport Boxes cleaning
4. Transport boxes permanent lining with soft material
5. Packaging of boxes inside cardboard (cardboard type, number of boxes inside one cardboard, how to arrange the boxes, packaging material)
6. How to open the boxes at the Assembly Sites
7. Requirements for the pTP evaporated NF/DF
8. Assembly
 - a. at Assembly sites: → define and test shipment procedures of the XA-MC
 - b. at SURF → check availability of a clean environment devoted to NF/DF integration into the XA-MC



- Avoid use of improper boxes
- comb ranking structure not good
- missing soft material below above glasses
- parcel not properly packaged

