

List of Talks, Fermilab Presenter, & Location

Session Title	Presenters	Location	Reviewers
Plenary Session <i>Tuesday October 1, 2013 - 8:15 - 12:00</i>			
<i>Welcome, Introductions, Safety Procedures</i>	John Anderson Jr.	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>Fermilab and the Intensity Frontier</i>	Nigel Lockyer	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>Accelerator Readiness Review Process and Plan</i>	John Anderson Jr.	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>MI, Recycler, & NuMI Modifications</i>	Paul Derwent	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>Radiation Protection Standards for Prompt Radiation Fields</i>	Don Cossairt	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>SA, SAD, ASE, & USI Review Processes and Current Document Status</i>	John Anderson Jr.	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>Overview of FESHCom, SA and SAD Subcommittees</i>	Don Cossairt	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>Beam Loss Scenarios Panel</i> <i>J. Anderson Jr.</i>	John Anderson Jr.	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>Credited Controls</i>	John Anderson Jr.	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>Lessons Learned - Response to Recent Accelerator Events</i>	John Anderson Jr.	Wilson Hall 1 East	ARR Committee and DOE Observers
<i>Industrial Hazard Mitigation FRCM and FESHM</i>	Don Cossairt	Wilson Hall 1 East	ARR Committee and DOE Observers

List of Talks, Fermilab Presenter, & Location

Session Title	Presenters	Location	Reviewers
Technical Breakout Session 1 <i>Tuesday October 1, 2013 - 13:15 - 14:45</i>			
<i>Safety Assessment Document (SAD) & Accelerator Safety Envelope (ASE)</i>	John Anderson Jr., Wayne Schmitt, Don Cossairt	Huddle AD Cross Gallery	Kornegay, Kestell
<i>Credited Controls (CC)</i>	Gary Lauten, Chuck Worel, MCR tour, Crew Chief	Bungalow AD Linac Annex	May, Parzyck
<i>Accelerator Operator Training and Qualification Program</i>	Dan Johnson, Duane Newhart	Dungeon AD Cross Gallery	Stanek, Soha
Technical Breakout Session 2 <i>Tuesday October 1, 2013 - 15:00 - 16:30</i>			
<i>Radiological Safety for 700 kW Operations</i>	Wayne Schmitt, John Anderson Jr., Gary Lauten, Ioanis Kourbanis, Dave Capista	Huddle AD Cross Gallery	Kornegay, Kestell
<i>Accelerator Safety and the Fermilab Contractor Assurance System (CAS)</i>	Martha Michaels, TJ Sarlina, Kathy Zappia, Don Cossairt	Woodshed WH 7W	May, Parzyck
<i>Accelerator Operations Procedures</i>	Dan Johnson, Duane Newhart	Dungeon AD Cross Gallery	Stanek, Soha
Tour <i>Wednesday October 2, 2013 - 8:00 - 12:00</i>			
<i>Main Injector/Recycler - MI-60</i>	Ioanis Kourbanis, Dave Capista, John Reid		ARR Committee and DOE Observers
<i>NuMI - MI-65 and MI-65 Underground</i>	Jim Hysten, Michael Andrews		ARR Committee and DOE Observers
<i>Main Control Room (MCR), Linac Gallery, Booster</i>	Dan Johnson, Duane Newhart, Bill Pellico		ARR Committee and DOE Observers
Technical Breakout Session 3 <i>Wednesday October 2, 2013 - 13:15 - 14:45</i>			
<i>Unreviewed Safety Issues (USI)</i>	John Anderson Jr., Don Cossairt	1 East Wilson Hall	Kornegay, Kestell
<i>Safety Configuration Management (SCM)</i>	Gary Lauten, Chuck Worel	Bungalow AD Linac Annex	May, Parzyck
<i>Work Planning and Control Related to Accelerator Safety</i>	Dan Johnson, Dave Augustine, Cons Gattuso, Duane Newhart	Dungeon AD Cross Gallery	Stanek, Soha