SeaQuest AEM Update

Bryan Ramson

University of Michigan


July 18th, 2016

Status Summary

- Target Transient Trouble
- DAQ & Trigger ROC Failure
- Chambers All Clear
- Hodoscopes All Clear

Status Summary

Accumulated Data



Details

Target

- Various H2 and D2 alarms sound spontaneously, despite stable target
- Isolated to failing cernox cryogenic temperature sensor on D2
- Still unsure of cause in H2

ROC 6 Failure

- A St. 1 DC TDC died and brought down ROC 6.
- After ROC replacement, could only read 3 of its 7 TDCs, we took ourselves out of the timeline Saturday night
- Returned the next morning and switched CPUs, all ROCs working after a single TDC replacement