Tuesday	Wednesday	Thursday	Friday
28	29	30	31
MS14 Electronics	MS13 Rigging	MS14 Rigging	MS15 Electroncis
	MSB lead worker	MSB lead worker	1 PM / Afternoon Elevator m
4 🛎	5 🛎	6 🛎	7 *
MS16 Electronics	MS15 Rigging	MS16 Rigging	MS17 Electronics
	MSB lead worker	MSB lead worker	
11	12	13	14
MS18 Electronics	MS17 Rigging	MS18 Rigging	MS19 Electronics
	MSB lead worker	MSB lead worker	
18	19	20	21
MS20 Electronics	MS19 Rigging	MS20 Rigging	MS21 Electronics
	MSB lead worker	Save module set	
25	26	27	28
MS22 Electronics	MS21 Rigging	MS22 Rigging	MS23 Electronics
	save ECAL	save ECAL	
Sep 1	2	3	4
MS24 Electronics	MS23 Rigging	MS24 Rigging	MS25 Electronics
	save HCAL	save HCAL	
	MS14 Electronics  4  MS16 Electronics  11  MS18 Electronics  18  MS20 Electronics  25  MS22 Electronics	MS13 Rigging MSB lead worker  MS15 Rigging MSB lead worker  MS16 Electronics MS17 Rigging MSB lead worker  11 12 MS18 Electronics MS17 Rigging MSB lead worker  18 19 MS20 Electronics MS19 Rigging MSB lead worker  25 26 MS21 Rigging Save ECAL  Sep 1 2 MS24 Electronics MS23 Rigging	MS14 Electronics  MS18 lead worker  MSB lead worker  MSCO Rigging  MSCO Rigging  Save module set  MSCO Rigging  MSCO Rigging  Save module set  MSCO Rigging  MSCO Rigging  Save module set  MSCO Rigging  MSCO Rigging  MSCO Rigging  Save module set  MSCO Rigging  MSCO Rigging

Monday	Tuesday	Wednesday	Thursday	Friday
Aug 31	Sep 1	2	3	4
MS23 Electronics	MS24 Electronics	MS23 Rigging	MS24 Rigging	MS25 Electronics
MS24 Electronics		save HCAL	save HCAL	
7	8	9	10	11
Labor Day	MS25 Electronics	MS25 Rigging	MS26 Electronics	MS27 Electronics
	MS26 Electronics	Save HCAL?		
14	15	16	17	18
MS26 Rigging Save HCAL?	MS27 Rigging Save HCAL?	® Rail and platform removal		
Jave FICAL:	Save FICAL:			
21	22	23	24	25
<b>©</b> RaiStart MINOS magnetic co	il removal			
20	20	20	0-1-1	2
28	29	30	Oct 1	2