

NuMI: 9AM Meeting

- Thu Dec 22nd & Fri Dec 23rd: I:KPS6N & I:KPS6S extraction kickers went into alarm: [elog230315](#), [elog230397](#) & [elog230399](#)
 - May be cold weather related
- Fri Dec 23rd & Wed Dec 28th: Low transformer oil level status for E:V108: [elog230346](#), [elog230379](#), [elog230399](#), & [elog230675](#)
 - Status is now cleared; sounds like it was cold weather related
 - Thanks to EE Support
- Sun Dec 25th: E:QD118 was spraying water: [elog230477](#) & [elog230659](#)
 - Thanks to Ops for finding and stopping the spraying water
 - Experts will meet next week to form a repair plan
- Mon Dec 26th to Fri Dec 30th: Horn & stripline work continues
 - Let experts describe work