

Managed by Fermi Research Alliance, LLC for the U.S Department of Energy Office of Science

Main Injector Operations Status


Osama Mohsen

Weekly meetings

10/03/23




NuMI Beam






Muon Beam





Switchyard Beam





Other issues

- RRXDMP (Recycler Ring Transverse Damper) node was reset on Monday.
- We had a random spike in the losses in RR and after investigating we found that QT604 had been operating at low current and started operating normal again (Thanks to M. Wren for this).
- BF work on BR station 2 and MI station 5
- We recovered well from the power outage,. MI and RR are ready for beam



Requests

• Studies: \$E1 and \$E0 studies

