




Mu2e Tracker Straw Assemblies




A. Mukherjee Tracker L2 Manager For M. Corcoran, Straw Assemblies L3 Manager 7/8/2014

Panel Assembly Jig


- Align parts for inner ring
- Align straws
- Align wires







Panel Assembly Jig




- Straw end alignment
- Position straw end to ~100µm
- Sufficient to ensure wire fits in pin
- Wire aligned
- Independent of straw position
- Use dowel pins to form "comb"



Panel Assembly Inner Ring


- Assemble inner ring from 5 parts
 - Lower SS ring and plastic inserts include alignment holes to engage on alignment jig
 - Epoxy plastic inserts and middle SS insert together with lower SS ring
 - Epoxy on upper SS ring



🔁 Fermilab

Panel Assembly Straws

- Insert, tension, and epoxy straws
 - Jig includes guides to align straw ends
- Install, tension, epoxy and solder wires
 - Jig includes "combs" to align wires






Mu2e

5

Panel Assembly Gas Manifold


- Epoxy on remainder of gas manifold
 - 6 pieces, all aluminum
 - Penetrations in outer ring not shown





Panel Assembly Covers

- Screw on cover plates
 - 3 pieces, all aluminum
 - Gas seal is with o-ring on covers






Mu₂e

7

Panel Rigidity

- Panel deformation due to straw tension
- Significant, but acceptable




Mu2e


8

🚰 Fermilab

Wire Position X-ray Scan



Wire Position Scan






Panel Leak Test

All panels are leak tested in vacuum before being assembled into planes

Vacuum vessel for panel leak testing








Plane Assembly


- Inner ring alignment holes at 15° intervals to allow alignment with 30° rotation
- Install cooling ring after assembling plane
- Panels get surveyed (optical) after tracker assembly




🛠 Fermilab

Tracker Assembly Beams


- Horizontal beams to tie planes together
- Top beam just maintains spacing
- Two lower beams support weight (transfer to rails) & act as cable trays
- Asymmetric to place cabling low while maintaining rigidity





Tracker Assembly


 Beams include clearance holes (not shown) to sight panel survey monuments





Cost Distribution by L4

Base Cost by L4 (AY \$k)




- 475.06.03 Straw Assemblies Actuals
- 475.06.03.01 Panels
- 475.06.03.02 Single Plane
- 475.06.03.03 Gas Manifold
- 475.06.03.04 Full Tracker Support and Assembly



Cost Distribution by Resource Type


Base Cost (AY \$k)





Quality of Estimate

Base Cost by Estimate Type (AY\$k)




L1 Actual / M1 Existing P.O.

- L3 / M3 Advanced
- L4 / M4 Preliminary
- L5 / M5 Conceptual



Labor Resources

FTEs by Discipline



18 A. Mukherjee – Tracker Straw Assemblies

Cost Table

Costs are fully burdened in AY \$k

	Base Cost (AY \$)					
	M&S	Labor	Total	Estimate Uncertainty (on remaining costs)	% Contingency on ETC	Total Cost
475.06.03 Straw Assemblies Actuals	85	146	231			231
475.06.03.01 Panels	688	184	873	415	48%	1,288
475.06.03.02 Single Plane	153	46	200	73	37%	273
475.06.03.03 Gas Manifold	1,869	153	2,022	822	41%	2,844
475.06.03.04 Full Tracker Support and Assembly	195	295	490	185	38%	674
Grand Total	2,991	824	3,815	1,495	42%	5,310

Mu2e

Summary

- Panel construction fixtures and procedures well defined
 - Starting assembly of first panel, with metal inner ring
 - After completion, this will be the test system for electronics and infrastructure
 - Start assembly of 2nd panel, with composite inner ring, immediately after (end of summer)
- Plane and tracker assembly progressing
 - More engineering effort starting this summer



Μιι2e